



Figure 4a:
VIEW OF RAVINE SIDE:
photo taken in Fall 2007

Note:

- Present state of house - after work was halted

Figure 4b:
VIEW OF RAVINE SIDE:
photo taken prior to most recent renovation (Fall 2006)

Note:

- Horizontal banding at fascia
- Large surfaces of material.
- Large surfaces of glass
- Controlled views at upper floor towards ravine
- Controlled views at lower floor perpendicular to ravine

