

Figure 4a: VIEW OF RAVINE SIDE: photo taken in Fall 2007

## Note:

Present state of house - after work was halted

Figure 4b: VIEW OF RAVINE SIDE: photo taken prior to most recent renovation (Fall 2006)

## Note:

- Horizontal banding at fascia
- Large surfaces of material.
- Large surfaces of glass
- Controlled views at upper floor towards ravine
- Controlled views at lower floor

perpendicular to ravine



Top, Fall 2007 after work commenced on current building permit

Bottom, Fall 2006