

MLS Building Audit Program - Details

Property Address: 1760 WILSON AVE

Legal Description: PLAN 3855 PT BLK G

Roll No. : 1908011040012000000 Building : **1760 WILSON AVE**

Report Date: January 18, 2019

Building Audit Date : February 07, 2013

** Please Note **

The information contained within this report represents the level of investigation activity for the referenced building as conducted through the Building Audit Program, up to January 18, 2019

Part I - Building Audit Activity Summary:

No.	Type of Investigation	Investigation Reference No.	Investigation Description	Investigation Status	Date of Issuance	Expiration Date	% Complied
1	Property Standards	13 117635 PRS 00 IV	EXTERIOR COMMON ELEMENTS - DEFECTS	Closed	13-Feb-13	18-JUN-13	100.00%
2	Property Standards	13 117638 PRS 00 IV	INTERIOR COMMON ELEMENTS - DEFECTS	Closed	13-Feb-13	14-MAY-13	100.00%

Note: N/A* - Not Applicable. For these notices the expectation for compliance is conveyed as immediate/forthwith upon issuance.

N/A** - Not Applicable. For these Notices/Orders partial compliance is not valid.

Jan 19, 2019 4:44 By Scheduler Version: MLSIV299.20120803 Page 1 of 3

Part II - Building Audit Details for Property Standards Orders :

	No.	''	Investigation Reference No.	Investigation Description	Investigation Status	Date of Issuance	=xp.:at.o	Next Scheduled Inspection Date
ŀ	1	Property Standards	13 117635 PRS 00 IV	EXTERIOR COMMON ELEMENTS - DEFECTS	Closed	13-Feb-13	18-JUN-13	19-Jun-13

No. of defects contained within the Order : 7

No. of defects that remain outstanding : 0

	Deficiency Details					
No.	Violation/Defect	Location	Status			
1	Concrete window sills damaged and deteriorated.	Building	Closed			
2	Paint peeling and deteriorated.	East Side of Building	Closed			
3	Section of wood fascia has hole.	Front	Closed			
4	Areas of deteriorated bricks and mortar.	Front	Closed			
5	Area of mortar missing between blocks.	West	Closed			
6	One board missing.	West Side of Building	Closed			
7	Exterior garbage containment area not screened.	Yard	Closed			

No.	''	Investigation Reference No.	Investigation Description	Investigation Status	Date of Issuance	Expiration Date	Next Scheduled Inspection Date
2	Property Standards	13 117638 PRS 00 IV	INTERIOR COMMON ELEMENTS - DEFECTS	Closed	13-Feb-13	14-MAY-13	15-May-13

No. of defects contained within the Order : 7

No. of defects that remain outstanding : 0

	Deficiency Details				
No.	Violation/Defect	Location	Status		
1	Corridors are not equipped to provide illumination to an average level of not less than 50 lux at floor or tread level.	Interior of Building	Closed		
	East stairwell is not equipped to provide illumination to an average level of not less than 50 lux at floor or tread level.	Interior of Building	Closed		
	West stairwell is not equipped to provide illumination to an average level of not less than 50 lux at floor or tread level.	Interior of Building	Closed		
4	Lighting in boiler room is provided at less than 200 lux.	Interior of Building	Closed		
5	The boiler room ceiling has a hole.	Interior of Building	Closed		
6	Boiler room wall has a section of missing blocks	Interior of Building	Closed		
7	The 4th floor east door will not close.	Interior of Building	Closed		

 Jan 19, 2019 4:44 By Scheduler
 Version: MLSIV299.20120803
 Page 2 of 3

Part III - Apartment Unit Activity Summary for Property Standards Orders :

	Active apartment unit related investigation matters (Property Standards only) :	0
	Number of investigation-related Orders issued to Property owner:	0
I	Number of investigation-related Orders issued to tenants :	0

^{*} Note: The number of unit related orders relate to all buildings on the above property.