

PHOTOGRAPHS:
69 LONG BRANCH AVENUE AND 24 MARINA AVENUE

ATTACHMENT NO. 2



Showing the south elevations of the former St. Agnes' Church, 69 Long Branch Avenue and the rectory at 24 Marina Avenue (right) with the office/chapel link between the two.
(Heritage Preservation Services 2016)



Showing the west and south elevations of former St. Agnes' Church, 69 Long Branch Avenue with the church, spire and narthex (entry) block. *(Heritage Preservation Services 2016)*



Showing the original interior of St. Agnes' Church nave looking north towards the altar.
(https://lostanglicanchurches.files.wordpress.com/2013/10/img_9543-medium.jpg)



Showing the St. Agnes's Church interior of the nave looking south towards the entrance.
(HPS 2016)