

SV1.5.3

submission from
RTEK2RA, MSO.

PHOTO#

Sent email to tenant, awaiting response

y Documentation	Process Deficiency		3	1. Basement Bathroom - The supplied facility in or on the property is not constructed, installed and/or maintained so that it will function safely and effectively. Namely, bathroom tub has deteriorated and missing sealant	N/A	
y Documentation	Process Deficiency		2	2. Basement Bathroom - The ventilation system or unit is not regularly cleaned. Namely, the bathroom vent fan is blocked by dust/debris	N/A	
y Documentation	Process Deficiency		4	3. Bathroom Basement - Vanity is not maintained in a satisfactory condition. Namely, vanity is loose from wall and wobbles	N/A	
y Documentation	Process Deficiency		4	4. Bathroom Basement - Vanity is not maintained in a satisfactory condition. Namely, vanity has deteriorated materials on the side and underside of counter	N/A	
y Documentation	Process Deficiency		⑤	5. Bedroom - Wall(s) not maintained free of holes, cracks, damaged and deteriorated materials. Namely, large gap under window frame of main bedroom	N/A	
y Documentation	Process Deficiency		6+7	6. Entranceway side entrance - Wall(s) not maintained free of holes, cracks, damaged and deteriorated materials. Namely, entranceway from side entrance to basement has deteriorated materials inside	N/A	
y Documentation	Process Deficiency		8+9	7. Throughout Dwelling Unit Basement - Exterior window not maintained weather-tight. Namely, windows are missing sealant and have evidence of water permeating	N/A	


CO

101

THE UNIVERSITY OF
THE SOUTH ALABAMA


INFORMATION


2




4

5







(K3)

