TORONTO

STAFF REPORT
INFORMATION ONLY

Supplementary Report: All Way Stop Control - Armour Boulevard and Romney Road

Date:	April 24, 2015
To:	North York Community Council
From:	Director, Transportation Services, North York District
Wards:	**Ward 10 – York Centre**
Reference Number:	*p:/20150Cluster/TRA/NorthYork/ny15047*

SUMMARY

This supplementary report was requested in connection with item number NY5.13 entitled All Way Stop Control: Armour Boulevard and Romney Road, at its meeting of April 14, 2015.

The purpose of this report is to provide the North York Community Council with a map of all speed hump traffic calming measures, stop signs and posted speeds on the following route: Bathurst Street and York Downs Drive to Armour Road, southbound to Bombay Avenue and eastward to the point of Avenue Road.

Financial Impact

There is no financial impact to the City as a result of this information report.

DECISION HISTORY

Transportation Services reported on the installation of an All-Way Stop Control at the intersection of Armour Boulevard and Romney Road, at the request of the Ward Councillor, which was deferred from North York Community Council's meeting of April 14, 2015:

http://app.toronto.ca/tmmis/viewAgendaItemHistory.do?item=2015.NY5.13

The above-noted report was subsequent to a report to respond to a request to install an All-Way Stop Control at the intersection of Armour Boulevard and Romney Road, which was denied at North York Community Council on November 19, 2013:

http://app.toronto.ca/tmmis/viewAgendaItemHistory.do?item=2013.NY28.8

COMMENTS

At the request of the Council, Transportation Services prepared a map, attached to this report, which shows all speed hump traffic calming measures, stop signs, posted speeds and turn prohibitins that are in place along the following route: Bathurst Street and York Downs Drive to Armour Road, southbound to Bombay Avenue and eastward to the point of Avenue Road.

The Council also requested that Transportation Services provide any recent traffic and speed monitoring data along the same route as noted above. A search of our records for the period between 2010 and 2015 indicates that there have been no speed or volume studies completed during this period.

CONTACT

Shawn Dillon
Manager, Traffic Operations
Transportation Services Division, North York District
Tel: 416-395-7463 Fax: 416-395-7544
Email: sdillon2@toronto.ca

SIGNATURE

_____
Jacqueline White, P. Eng.
Director

ATTACHMENTS

Attachment 1: Map – Intersection of Armour Blvd and Romney Rd: Requested AWSC