

TWSI REVIEW NEEDED

NINTH ST & LAKE SHORE BLVD W



TWSI: NORTHEAST AND SOUTHEAST CORNERS

APS + TWSI REVIEW NEEDED

TENTH ST & LAKE SHORE BLVD W



TWSI: NORTHEAST CORNER

TWSI REVIEW NEEDED

TWELFTH ST & LAKE SHORE BLVD W

ISLAND CROSSING



APS + TWSI REVIEW NEEDED

THIRTEENTH ST & LAKE SHORE BLVD

W



TWSI: NORTHEAST AND SOUTHEAST CORNERS

TWSI REVIEW NEEDED

FIFTEENTH ST & LAKE SHORE BLVD W



TWSI: NORTH CROSSING, BOTH SIDES

SUMMARY



TACTILE INDICATORS NEEDED AT:

Eighth St. & Birmingham St.	Southeast corner, tactile plates needed
Ninth St. & Birmingham St.	Southwest corner, tactile plates needed
William Jackson Way & Birmingham St.	South crossing, no plates or engraved lines
Fifth St. & Lake Shore Blvd. W	Northeast, Northwest and Southeast corner
Ninth St. & Lake Shore Blvd. W	No plate or engraved lines on Northeast corner
Tenth St. & Lake Shore Blvd. W	Northeast corner
Twelfth St. & Lake Shore Blvd. W	No plates or engraved lines on island crossing
Thirteenth St. & Lake Shore Blvd. W	Northeast and Southeast corners
Fifteenth St. & Lake Shore Blvd. W	No plates or engraved lines on either side of North crossing



ACCESSIBLE PEDESTRIAN SIGNALS NEEDED AT

IslingtonAve.&BirminghamSt.A
KiplingAve.&BirminghamSt.A
FifthSt.&LakeShoreBlvd.AVA
TenthSt.&LakeShoreBlvd.AVA
ThirteenthSt.&LakeShoreBlvd.AVA