

Parking Amendments - Milepost Place

Date: June 18, 2026

To: North York Community Council

From: Director, Enforcement and Street Management, Transportation Services

Wards: Ward 15 - Don Valley West

SUMMARY

This staff report is about a matter that Community Council has delegated authority from City Council to make a final decision.

Transportation Services is recommending that stopping be prohibited on the north side of Milepost Place, between Thorncliffe Park Drive and a point 15 metres west, and on the south side, between Thorncliffe Park Drive and a point 20 metres west. Currently parking is prohibited at all times on these segments of Milepost Place. The proposed stopping prohibition will address stopped vehicles unloading on these segments, which obstructs traffic at the intersection.

RECOMMENDATIONS

The Director, Enforcement and Street Management, Transportation Services recommends that:

1. North York Community Council prohibit stopping at all times on the north side of Milepost Place, between Thorncliffe Park Drive and a point 15 metres west.
2. North York Community Council prohibit stopping at all times on the south side of Milepost Place, between Thorncliffe Park Drive and a point 20 metres west.

FINANCIAL IMPACT

The signage costs associated with the proposed amendments are approximately \$1,000. Funding is available within the Transportation Services 2026 Operating Budget.

DECISION HISTORY

This report addresses a new initiative.

COMMENTS

The Ward Councillor, on behalf of nearby residents, requested that stopping be prohibited at all times on both sides of Milepost Place, in the vicinity of Thorncliffe Park Drive, in order to ensure that the intersection is not obstructed.

Existing Conditions

Milepost Place is characterized by the following conditions:

- It is two-lane, north-south local roadway
- It operates two-way traffic on a pavement width of approximately 8.5 metres
- The daily two-way traffic volume is approximately 600 vehicles
- The speed limit is 50 km/h
- Heavy trucks are permitted at all times
- There is no TTC service
- There are sidewalks on both sides of the street

The parking regulations on Milepost Place are as follows:

North side

- No parking anytime, between Thorncliffe Park Drive and a point 15 metres west
- Unsigned statutory three-hour maximum parking limit on remainder of street

South side

- No parking anytime, between Thorncliffe Park Drive and a point 20 metres west
- No standing anytime (car-share vehicles excepted), between a point 20 metres west of Thorncliffe Park Drive and a point 11 metres west further west
- Unsigned statutory three-hour maximum parking limit on remainder of street

Proposed Changes

Observations revealed that grocery produce is often unloaded and sold from the rear of a vehicle parked on Milepost Place in the vicinity of Thorncliffe Park Drive, sometimes close to the intersection where parking is prohibited. This activity obstructs traffic at the intersection. Amending the parking prohibition to a stopping prohibition would prohibit unloading in this area and mitigate this situation.

A map of the area and proposed parking amendments is included in Attachment 1.

The Ward Councillor has been advised of the recommendations of this staff report.

CONTACT

Shawn Dillon, Manager Traffic Operations (Area 2), Transportation Services, 416-394-8409, Shawn.Dillon@toronto.ca

SIGNATURE

Mike Barnet, P. Eng.
Director, Enforcement and Street Management, Transportation Services

ATTACHMENTS

Attachment 1: Map - Parking Amendments - Milepost Place

Attachment 1: Map - Parking Amendments - Milepost Place

