



**STAFF REPORT
ACTION REQUIRED**

Proposed Minor Street Stop Signs – Treverton Drive Area

Date:	January 20, 2010
To:	Scarborough Community Council
From:	Acting Director, Transportation Services, Scarborough District
Wards:	Ward 37 – Scarborough Centre
Reference Number:	P:\2010\Cluster B\TRA\Scarborough\sc1019 D09-3415743 Treverton area stop signs

SUMMARY

This staff report is about a matter for which the Community Council has delegated authority from City Council to make a final decision.

During an operational review in the Treverton Drive area, Transportation Services staff identified eleven uncontrolled three-way intersections in the immediate area of Treverton Drive and Stratton Avenue.

It is recommended that minor street stop signs be installed at the subject eleven uncontrolled three-way intersections to clearly define the right-of-way and to regulate traffic flow.

RECOMMENDATIONS

Transportation Services, Scarborough District, recommends that Scarborough Community Council:

1. Enact the compulsory stops and through streets regulation(s), as identified in Appendix 1 of this report.
2. Amend the appropriate by-law(s) accordingly.

Financial Impact

The financial cost of installing the subject recommended stop controls is approximately \$3,000.00. The funding for these stop controls is available in the Transportation Services 2010 Operating Budget, within Cost Centre TP0397.

ISSUE BACKGROUND

Transportation Services staff identified eleven uncontrolled three-way intersections in the immediate area.

COMMENTS

The following characteristics describe the subject eleven uncontrolled three-way intersections:

- The eleven locations of the uncontrolled stops include: Sedgewick Crescent at Treverton Drive (south intersection), Sedgewick Crescent at Treverton Drive (north intersection), Oakworth Crescent at Treverton Drive (south intersection), Oakworth Crescent at Treverton Drive (north intersection), Moorecroft Crescent at Treverton Drive (south intersection), Moorecroft Crescent at Treverton Drive (north intersection), Stratton Avenue at Treverton Drive, Shenley Road at Treverton Drive, Treverton Drive at Mooregate Avenue, Shenley Road at Mooregate Avenue, Mooregate Avenue at Stratton Avenue.
- The subject uncontrolled three-way intersections are all located in the community east of Kennedy Road, north of Eglinton Avenue East, and south of Lawrence Avenue East, within the Ionview neighbourhood.
- Approximately half of these roadways have sidewalks.
- The land use of this neighbourhood is primarily single family residential.

Minor street stop signs are recommended at the subject eleven uncontrolled three-way intersection locations. When installed the signs will provide stop sign uniformity, clearly define the right-of way, and enhance driver and pedestrian safety.

CONTACT

Marko A. Oinonen, P.Eng.
Manager, Traffic Operations, Scarborough District
Tel: 416-396-7148
Fax: 416-396-5641
E-Mail: moinone@toronto.ca

SIGNATURE

Steven T. Kodama, P.Eng.
Acting Director, Transportation Services, Scarborough District

JE:ca

ATTACHMENTS

1. Appendix 1 – By-law Amendment (enact)
2. Location Plan (Proposed Stop Signs – Treverton Drive Area)

Appendix 1

“Compulsory Stops”
Regulation to be Enacted

Column 1
Intersection

Column 2
Stop Street

Treverton Drive and Mooregate Avenue

Treverton Drive

Shenley Road and Mooregate Avenue

Shenley Road

Mooregate Avenue and Stratton Avenue

Mooregate Avenue

“Through Streets”
Regulation to be Enacted

(In
Column 1)
Highway

(In
Column 2)
From

To

Treverton Drive

Kennedy Road

Mooregate Avenue