

**MLS Building Audit Program - Details**

**Property Address : 55 WYNFORD HEIGHTS CRES**

Legal Description: PLAN M1176 BLK D

Roll No. : 1908101050003000000

Building : **55 WYNFORD HEIGHTS CRES**

**Report Date : January 17, 2020**

**Building Audit Date : October 31, 2011**

**\*\* Please Note \*\***

The information contained within this report represents the level of investigation activity for the referenced building as conducted through the Building Audit Program, up to January 17, 2020

**Part I - Building Audit Activity Summary :**

| No. | Type of Investigation | Investigation Reference No. | Investigation Description          | Investigation Status | Date of Issuance | Expiration Date | % Complied |
|-----|-----------------------|-----------------------------|------------------------------------|----------------------|------------------|-----------------|------------|
| 1   | Property Standards    | 11 302499 PRS 00 IV         | PARKING GARAGE/STRUCTURE - DEFECTS | Closed               | 10-Nov-11        | 08-MAY-12       | 100.00%    |
| 3   | Property Standards    | 11 302668 PRS 00 IV         | INTERIOR COMMON ELEMENTS - DEFECTS | Closed               | 10-Nov-11        | 08-MAY-12       | 100.00%    |
| 4   | Property Standards    | 11 302679 PRS 00 IV         | EXTERIOR COMMON ELEMENTS - DEFECTS | Closed               | 10-Nov-11        | 08-FEB-12       | 100.00%    |

**Note :** N/A\* - Not Applicable. For these notices the expectation for compliance is conveyed as immediate/forthwith upon issuance.  
 N/A\*\* - Not Applicable. For these Notices/Orders partial compliance is not valid.

## Part II - Building Audit Details for Property Standards Orders :

| No. | Type of Investigation | Investigation Reference No. | Investigation Description          | Investigation Status | Date of Issuance | Expiration Date | Next Scheduled Inspection Date |
|-----|-----------------------|-----------------------------|------------------------------------|----------------------|------------------|-----------------|--------------------------------|
| 4   | Property Standards    | 11 302679 PRS 00 IV         | EXTERIOR COMMON ELEMENTS - DEFECTS | Closed               | 10-Nov-11        | 08-FEB-12       | 15-Oct-12                      |

No. of defects contained within the Order : **8**

No. of defects that remain outstanding : **0**

| Deficiency Details |   |                       |                  |
|--------------------|---|-----------------------|------------------|
| No.                | Violation/Defect  | Location              | Status           |
| 1                  | Immediate action has not been taken to eliminate an unsafe condition. Where window air-conditioner's installation prevents a safety device from being installed a report is required to be submitted to the Officer for evaluation and approval by a professional or other certified person confirming that acceptable to ensure that the installation of the air-conditioner is done safe and securely; that there are no openings greater than one hundred (100) millimetres adjacent to the air conditioning unit and that the electrical supply and distribution in the suite is capable of safely operating the air conditioning unit. Also it must address any remedial action that must be taken in order to maintain its safe manner. | Building              | Closed           |
| 2                  | The exterior surface of the building shall be maintained free of graffiti and/or painted slogans. Namely: East side exit door. Graffiti on stairway exit door and wall.   | East Side of Building | Closed           |
| 3                  | The (verandah, porch, deck, loading dock, ramp, balcony, fire escape or other similar structure, and/or other appurtenant attachment) and/or the supporting structural member(s) is not maintained in good repair. Namely: East side of building. Deteriorated concrete on balcony slabs with exposed reinforcing bars.   | East Side of Building | Closed           |
| 4                  | Immediate action has not been taken to eliminate an unsafe condition..Namely; the structural integrity of the attachment of all satellite dishes affixed to the building, or the building components. A report is required to be submitted to the Officer for evaluation and approval by a professional or other certified person confirming that Satellite Dishes have been installed safely in an acceptable manner, the report must address any remedial action that must be taken in order to maintain the structural integrity of the attachment and that attachment of all satellite dishes affixed to the building are done in a safe and secure manner.   | Exterior of Building  | Closed           |
| 5                  | A window(s) which is capable of being opened, and is located in excess of two (2) metres from the finished grade, is not equipped with safety devices which would prevent any opening greater than one hundred (100) millimeters. A report is required to be submitted to the Officer for evaluation and approval by a professional or other certified person confirming that acceptable safety devices have been installed on all subject windows in an acceptable manner, and that the subject windows are not capable of being opened in excess of one hundred (100) millimeters.  | Throughout Building   | Closed           |
| 6                  | The protective/decorative finish on the exterior surfaces is not being maintained in good repair. Namely: Deteriorated surface paint finish on exterior garage doors on the west side of building.  | West Side of Building | Closed           |
| 7                  | Required guard does not prevent the passage of a spherical object having a diameter more than 100 millimetres. Namely: Exterior guards for exits from underground garage, space at the bottom of the guard is greater than 100mm. Repairs required.   |                       | Substantially Co |
| 8                  | The fence, screen and/or other enclosure around or on the property is not being maintained in good repair. Namely: Exterior fence enclosure for swimming pool, broken boards and holes in the fence should be repaired.   |                       | Closed           |

| No. | Type of Investigation | Investigation Reference No. | Investigation Description          | Investigation Status | Date of Issuance | Expiration Date | Next Scheduled Inspection Date |
|-----|-----------------------|-----------------------------|------------------------------------|----------------------|------------------|-----------------|--------------------------------|
| 1   | Property Standards    | 11 302499 PRS 00 IV         | PARKING GARAGE/STRUCTURE - DEFECTS | Closed               | 10-Nov-11        | 08-MAY-12       | 31-Dec-16                      |

No. of defects contained within the Order :

No. of defects that remain outstanding :

| Deficiency Details |  |                          |                  |
|--------------------|--|--------------------------|------------------|
| No.                | Violation/Defect   | Location                 | Status           |
| 1                  | The ceilings in the parking or storage garage are not impervious to water.   | Underground Parking Area | Closed           |
| 2                  | The parking or storage garage walls from floor level to a height of sixty (60) centimeters are not painted black where required.   | Underground Parking Area | Closed           |
| 3                  | The electrical connections are not maintained in a safe and complete condition. Namely; missing cover plates.  | Underground Parking Area | Substantially Co |
| 4                  | The ceilings in the parking or storage garage are not maintained free of holes, breaks or cracks.  | Underground Parking Area | Substantially Co |
| 5                  | Lighting in a garage is provided at less than 50 lux.  | Underground Parking Area | Closed           |
| 6                  | Lighting in a service room is provided at less than 200 lux.   | Underground Parking Area | Closed           |
| 7                  | The electrical connections are not maintained in a safe and complete condition. Namely; loose wires.   | Underground Parking Area | Closed           |
| 8                  | The electrical connections are not maintained in a safe and complete condition. Namely; cover plates.  | Underground Parking Area | Closed           |
| 9                  | The electrical switches are not maintained in good working order.  | Underground Parking Area | Substantially Co |
| 10                 | Required guard does not prevent the passage of a sphere having a diameter more than 100 millimetres.   | Underground Parking Area | Closed           |
| 11                 | The parking or storage garage ceiling are not painted white.   | Underground Parking Area | Closed           |
| 12                 | The parking or storage garage is used to keep junk or rubbish.   | Underground Parking Area | Substantially Co |
| 13                 | The floors in the parking or storage garage are not maintained free of holes, breaks or cracks   | Underground Parking Area | Closed           |
| 14                 | The plumbing system is not kept in good working order. Namely; damaged pipe.   | Underground Parking Area | Closed           |
| 15                 | The guard is designed that a member, attachment or opening located between 140 millimetres and 900 millimetres above the level being protected facilitates climbing.   | Underground Parking Area | Closed           |
| 16                 | The plumbing system is not kept in good working order. Namely; missing drain covers.   | Underground Parking Area | Closed           |
| 17                 | The walls in the parking or storage garage are not maintained free of holes, breaks or cracks.   | Underground Parking Area | Substantially Co |
| 18                 | The walls in the parking or storage garage are not impervious to water.  | Underground Parking Area | Substantially Co |
| 19                 | The parking or storage garage is used to keep junk or rubbish.   | Underground Parking Area | Closed           |
| 20                 | The electrical connections are not maintained in a safe and complete condition. Namely; loose wires.   | Underground Parking Area | Substantially Co |
| 21                 | Lighting in a storage room is provided at less than 50 lux.  | Underground Parking Area | Closed           |
| 22                 | The parking or storage garage walls are not painted white from sixty (60) centimeters above floor level where required.  | Underground Parking Area | Closed           |
| 23                 | Previously finished surface(s) have marks, stains, graffiti, smoke damage, painted slogans and/or other defacements.   | Underground Parking Area | Closed           |
| 24                 | Ceiling not maintained free of holes, cracks, damaged and deteriorated materials. Namely; missing access hatch.  | Underground Parking Area | Closed           |
| 25                 | Height of the guard for exit ramps and landings is less than 1,070 millimetres measured vertically to the top of the guard from the ramp surface where the difference in elevation between the adjacent ground or floor level and the ramp is more than 600 millimetres. | Underground Parking Area | Closed           |

| No. | Type of Investigation | Investigation Reference No. | Investigation Description          | Investigation Status | Date of Issuance | Expiration Date | Next Scheduled Inspection Date |
|-----|-----------------------|-----------------------------|------------------------------------|----------------------|------------------|-----------------|--------------------------------|
| 3   | Property Standards    | 11 302668 PRS 00 IV         | INTERIOR COMMON ELEMENTS - DEFECTS | Closed               | 10-Nov-11        | 08-MAY-12       | 11-Oct-12                      |

No. of defects contained within the Order : **31**

No. of defects that remain outstanding : **0**

| Deficiency Details |  |                     |        |
|--------------------|--|---------------------|--------|
| No.                | Violation/Defect   | Location            | Status |
| 1                  | Previously finished wall(s) in the public area of the property is not maintained in good repair. Namely: 3rd floor stairway. A section of baseboard is missing from the wall.  | 3rd Floor           | Closed |
| 2                  | The electrical fixtures are not maintained in good repair. Namely: 10th floor garbage room. Electrical cover plate is missing.   | 10th Floor          | Closed |
| 3                  | The electrical fixtures are not maintained in a safe and complete condition. Namely: 10th floor. Electrical light fixture is not secured properly to the ceiling. Near unit 1008. Repairs are required.              | 10th Floor          | Closed |
| 4                  | Previously finished surface(s) in the public area of the property is not maintained in good repair. Namely: Crack/broken plaster on ceiling near expansion joint.  | 12th Floor          | Closed |
| 5                  | The electrical fixtures are not maintained in good repair. Namely: Garbage room light fixture is in need of repair.  | 17th Floor          | Closed |
| 6                  | The floor drain is not maintained in good repair. Namely: Boiler room. Replace missing floor drain cover. Also replace a cracked floor drain cover.  | Boiler Room         | Closed |
| 7                  | Lighting in a service room is provided at less than 200 lux. Namely: Boiler Service room. Upgrade lighting at floor level to 200 Lux. Replace missing electrical cover plates. Secure all loose/hanging wires.       | Boiler Room         | Closed |
| 8                  | Garbage chute system originally installed in the multiple-dwelling is not maintained operative. Namely: On the 20th,15th, 11th and 9th floors, garbage chutes are required to be self-closing. Repairs are required. | Garbage Room        | Closed |
| 9                  | Lighting in a laundry room is provided at less than 200 lux. Namely: Upgrade lighting condition at floor level to 200 Lux. Replace missing cover plate on wall fixture.  | Laundry Room        | Closed |
| 10                 | Required handrails on stairs or ramps are less than 865mm or more than 965mm high. Namely: Required height for stairway handrails.   | Stairway            | Closed |
| 11                 | Required guard does not prevent the passage of a spherical object having a diameter more than 100 millimetres. Namely: Stairway landing and stair guards.  | Stairway            | Closed |
| 12                 | Handrails on both sides of stair or ramp 1,100mm in width or more not provided. Namely: An additional handrail is required on the wall of both stairways.  | Stairway            | Closed |
| 13                 | Floor and/or floor covering not kept in a clean and sanitary condition. Namely: Throughout building, all floors inside electrical closets, cleaning is required.   | Throughout Building | Closed |
| 14                 | Ceiling not maintained free of holes, cracks, damaged and deteriorated materials. Namely: Throughout building, areas where the ceiling tiles are water stained, replacement is required.                             | Throughout Building | Closed |
| 15                 | Handrails on both sides of stair or ramp 1,100mm in width or more not provided. Namely: Basement level stairway. A 2nd handrail is required on the wall.   |                     | Closed |
| 16                 | Previously finished wall(s) in the public area of the property is not maintained in good repair. Namely: Baseboard to be secured to wall properly in the stairway between 16th and 15th floors.                      |                     | Closed |
| 17                 | Wall(s) not maintained free of holes, cracks, damaged and deteriorated materials. Namely: Paint peeling on wall in stairway to elevator room, above access door.   |                     | Closed |
| 18                 | Floor and/or floor covering not kept in a clean and sanitary condition. Namely: 12th flr. Bell Telephone service room. Clean and clear floor of debris.  |                     | Closed |
| 19                 | The electrical connections are not maintained in good repair. Namely: 11th and 8th floor electrical closet. Loose electrical wires in red, to be secured properly.   |                     | Closed |
| 20                 | The electrical switches are not maintained in a safe and complete condition. Namely: Replace missing light switch cover plate. Near access door to roof level.   |                     | Closed |
| 21                 | The electrical fixtures are not maintained in a safe and complete condition. Namely: Men's Sauna Room. Missing lens cover on light fixture.  |                     | Closed |
| 22                 | The electrical fixtures are not maintained in a safe and complete condition. Namely: Electrical cover plate is missing on wall outlet.   |                     | Closed |
| 23                 | Ceiling not maintained free of holes or access hatch door. Namely: Women's Sauna room. Missing access hatch door in ceiling.   |                     | Closed |

|    |   |  |        |
|----|---|--|--------|
| 24 | Ceiling not maintained free of holes, cracks, damaged and deteriorated materials. Namely: Locker Room #7, 43 to 90. Repair hole in ceiling, near locker # 79.   |  | Closed |
| 25 | The ventilation system or unit is not kept in good repair and maintained in good working condition at all times. Namely: Missing radiator cover in elevator room.   |  | Closed |
| 26 | The (stairs, treads, risers, guards, handrails, and/or other appurtenant attachments) and/or their supporting structural members are not being maintained free from defects/hazards. Namely: From the 2nd flr. stairway to ground floor. Replace missing stairway tread strips.                     |  | Closed |
| 27 | Elevator machine room is not equipped to provide illumination to an average level of not less than 100 lux at floor level. Namely: Upgrade lighting in the lower level of elevator room to 100 Lux.   |  | Closed |
| 28 | Lighting in a storage room is provided at less than 50 lux. Namely: All Locker rooms, lighting to be upgraded to 50 lux at floor level.   |  | Closed |
| 29 | The location and size of openings present a hazard as they are designed with members or attachments between 140 millimetres and 900 millimetres above the level protected by the guard which facilitate climbing. Namely: Stairway landing and stair guards. Design of guards facilitates climbing. |  | Closed |
| 30 | The location and size of openings present a hazard as they are designed with members or attachments between 140 millimetres and 900 millimetres above the level protected by the guard which facilitate climbing. Namely: Landing and Stair guards.   |  | Closed |
| 31 | Required guard does not prevent the passage of a spherical object having a diameter more than 100 millimetres. Namely: Landing and stair guards.  |  | Closed |

## Part III - Apartment Unit Activity Summary for Property Standards Orders :

|  |          |
|--|----------|
| <b>Active apartment unit related investigation matters (Property Standards only) :</b> | <b>0</b> |
| Number of investigation-related Orders issued to Property owner :                      | 0        |
| Number of investigation-related Orders issued to tenants :                             | 0        |

**\* Note: The number of unit related orders relate to all buildings on the above property.**