
Appendix M

Erosion Control Structures

Erosion Assets						Erosion Structure Monitoring Records TRCA ID - US									
Structure ID	TRC A-ID	Inventory ID	Who Built	Who Owns	Land Owner	Structure Type	Primary Material	Maintenance Priority	Last Edited	Property Owner	Structure Type	Primary Material	Structure Stability	Overall Condition	Maintenance Type
DR109.04	DR10 9.04	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Retaining Wall	Armourstone	None	26-Mar-18	Hydro	NA	NA	NA	NA	NA
DR109.10	DR10 9.10	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Culvert	Corrugated Metal Pipe	Low	26-Mar-18	Hydro	Culvert	Corrugated Metal Pipe	Stable	Good	Minor
DR109.11	DR10 9.11	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Revetment	Rip Rap	Low	26-Mar-18	Hydro	Revetment	Rip-Rap	Failing	Fair	Minor
DR109.05	DR10 9.05	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Revetment	Rip Rap	Low	26-Mar-18	Hydro	Revetment	Rip-Rap	At Risk	Good	Minor
DR109.01	DR10 9.01	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Drainage Swale	Rip Rap	Low	26-Mar-18	Hydro	Drainage Swale	Rip-Rap	At Risk	Good	Minor
DR39.3	DR39 .3	D-28-37	TRCA	TRCA	TRCA	Revetment	Rip Rap	Low	31-Jul-18	TRCA	Revetment	Rip-Rap	At Risk	Good	Major
DR77	DR77	D-28-61.02	TRCA	TRCA	TRCA	Revetment	Fieldstone	Low	31-Jul-18	TRCA	NA	NA	NA	NA	NA
DR109.08	DR10 9.08	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Retaining Wall	Armourstone	None	26-Mar-18	Hydro	Retaining Wall	Armourstone	Stable	Excellent	None
DR62	DR62	D-16-64	Unknown	Assumption: TRCA (on City of Toronto Property, but no indication in CFN it is owned by the City)	TRCA	Revetment	Fieldstone	High	03-Sep-20	TRCA	Revetment	Fieldstone	Failing	Fair	Major
DR39.2	DR39 .2	D-28-35	TRCA	TRCA	Her Majesty the Queen (Party to Hydro Ontario)	Channelized	Armourstone	High	07-Jul-20	TRCA	Channelized	Armourstone	Failing	Fair	Major
DR109.09	DR10 9.09	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Revetment	Rip Rap	Low	26-Mar-18	Hydro	Revetment	Rip-Rap	Failing	Fair	Minor
DR109.12	DR10 9.12	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Drainage Sale	Rip Rap	Low	26-Mar-18	Hydro	Drainage Swale	Rip-Rap	At risk	Fair	Minor
DR109.03	DR10 9.03	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Retaining Wall	Armourstone	None	26-Mar-18	Hydro	Retaining Wall	Armourstone	Stable	Excellent	None
DR109.06	DR10 9.06	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Revetment	Rip Rap	Low	26-Mar-18	Hydro	Revetment	Rip-Rap	Failing	Good	Minor
DR109.07	DR10 9.07	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Retaining Wall	Armourstone	None	26-Mar-18	Hydro	Retaining Wall	Armourstone	Stable	Excellent	None
DR109.02	DR10 9.02	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Drainage Swale	Rip Rap	Low	26-Mar-18	Hydro	Drainage Swale	Rip-Rap	At risk	Good	Minor
DR39.1	DR39 .1	D-28-38	TRCA	TRCA	TRCA	Revetment	Rip Rap	High	07-Jul-20	TRCA	Revetment	Rip-Rap	Failed	Poor	Major
DR111.01	DR11 1.01	NA	TRCA	Sun Canadian Pipeline	TRCA	Buttress	Vegetated Rip Rap	Low	16-Aug-19	TRCA	Buttress	Vegetated Rip-Rap	Stable	Good	Minor
DR109.13	DR10 9.13	NA	Appco Paving Ltd. / TRCA	City of Toronto	Her Majesty the Queen (Party to Hydro Ontario)	Drainage Swale	Rip Rap	Low	26-Mar-18	Hydro	Drainage Swale	Rip-Rap	At risk	Fair	Minor