

Parking Prohibition: Hullmar Drive

Date:	May 10, 2007
To:	North York Community Council
From:	Acting Director, Transportation Services, North York District
Wards:	Ward 8 - York West
Reference Number:	p:\2007\ClusterB\TRA\NorthYork\nycc07049tsny (5059)

SUMMARY

This staff report is about a matter that the Community Council has delegated authority to make a final decision [provided that it is not amended so that it varies with City policy or by-laws].

To deny the request to remove the “No Parking Anytime” prohibition on the west side of Hullmar Drive, north of Skye Court.

The existing parking prohibitions are required to ensure that sightlines for motorists when exiting Skye Court are not restricted by parked vehicles.

RECOMMENDATIONS

Transportation Services, North York District recommends that:

1. the existing “No Parking Anytime” prohibitions on the west side of Hullmar Drive from the northerly limit of Skye Court to a point 40 metres northerly thereof, be retained.

FINANCIAL IMPACT

There is no financial impact associated with the adoption of this report.

ISSUE BACKGROUND

Transportation Services, North York District, was requested by Councillor Perruzza on behalf of a resident, to remove the “No Parking Anytime” prohibition on the west side of Hullmar Drive, north of Skye Court

COMMENTS

Currently, parking is prohibited at anytime on the west side of Hullmar Drive from the northerly limit of Skye Court to a point 40 metres north thereof and from the southerly limit of Skye Court to a point 15 metres south thereof. Parking is also prohibited on the west side of Hullmar Drive beyond the above-noted limits from 6:00 a.m. to 9:00 a.m. and 3:00 p.m. to 7:00 p.m., Monday to Friday. Parking is also prohibited at anytime on the entire east side of Hullmar Drive.

The parking prohibition on the west side of Hullmar Drive, north of Skye Court was implemented in 1995, at the request of the residents of Skye Court. The residents indicated that sightlines for eastbound motorists at the intersection were restricted and exiting motorists were unable to view oncoming southbound traffic on Hullmar Drive, thus creating a potentially hazardous traffic condition. These concerns were confirmed by staff and as such the parking prohibition was implemented.

As the conditions that supported the installation of the “No Parking Anytime” prohibitions still exist, this division cannot justify the removal of these prohibitions.

Councillor Anthony Perruzza has been advised of the recommendations contained in this staff report.

CONTACT

Martin D. Maguire, P. Eng.
Manager, Traffic Operations
Transportation Services, North York District
Tel: 416-395-7463
Fax: 416-395-7544
Email: mmaguir@toronto.ca

SIGNATURE

Pascoal D’Souza, C.E.T.
Acting Director

ATTACHMENTS

Attachment 1: Map – Hullmar Drive; Parking Prohibitions (ny0007049tsny_att1)