

May 3, 2007

To: Public Works and Infrastructure Committee

From: Scarborough Community Council

Subject: Feasibility of Installing Traffic Control Signals at the Intersection of  
Lawrence Avenue East and Elinor Avenue  
(Ward 37 – Scarborough Centre)

**Recommendations:**

**The Scarborough Community Council recommended that the Public Works and Infrastructure Committee and City Council:**

- 1. Receive the report (December 22, 2006) from the Director, Transportation Services, Scarborough District.**
- 2. Approve the installation of traffic control signals at the intersection of Lawrence Avenue East and Elinor Avenue.**

**Decision Advice and Other Information**

The Scarborough Community Council also requested the Director, Transportation Services, Scarborough District, to report to the Public Works and Infrastructure Committee for its meeting of May 30, 2007, such report to include recommended technical aspects of installing traffic control signals at this intersection specifically addressing the following:

- a. installation of islands and their impacts on adjacent businesses; and
- b. operational impacts on the adjacent intersection at Wexford Boulevard.

**Background:**

The Scarborough Community Council, on May 1, 2007, considered a report (December 22, 2006) from the Director, Transportation Services, Scarborough District, describing a review of the feasibility of installing traffic control signals at the intersection of Lawrence Avenue East and Elinor Avenue, and recommending that traffic control signals not be installed at this intersection at this time.

(for) City Clerk.

Betty Henderson, Manager, Community Councils & Committees

BH/mor

