



STAFF REPORT ACTION REQUIRED

Proposed Installation of Speed Bumps in Drummondville Lane

Date:	December 29, 2006
To:	Toronto and East York Community Council
From:	Director, Transportation Services Toronto and East York District
Wards:	Beaches – East York, Ward 32
Reference Number:	Ts07035tey.top.doc

SUMMARY

The purpose of this report is to obtain approval for the installation of speed bumps in a public lane.

RECOMMENDATIONS

Transportation Services recommends that:

1. the installation of speed bumps in Drummondville Lane, between William Hancox Avenue and Brockville Street, of the type and design noted and at the locations shown on Drawing No. 421F-8560 dated September 2006 be approved.

FINANCIAL IMPACT

Type of funding	Source of funds	Amount
Available within capital budget	Transportation Services Division Traffic Calming Account No. CTP- 806-06	\$2,000

ISSUE BACKGROUND

Councillor Sandra Bussin requested that Transportation Services staff review the feasibility of installing speed bumps in Drummondville Lane, between William Hancox Avenue and Brockville Street.

COMMENTS

According to guidelines as set out in City Council policy, the eligibility criteria for the installation of speed bumps in public lanes includes traffic volume (minimum of 100 vehicles per day), vehicular speed (average 20 km/h or greater) and pedestrian usage. One or more of the above three criteria must be met to warrant the installation of speed bumps.

The subject lane operates two-way in an east/west direction. The legal speed limit is 50 km/h.

A speed and volume survey conducted in the fall of 2006 revealed that this lane meets the installation criteria for speed bumps with respect to traffic volume (107 vehicles in 24 hours), vehicular speeds (average of 24 km/h) and pedestrian activity.

The locations of the speed bumps to be installed are shown on the attached Drawing No. 421F-8560 dated September 2006.

Councillor Sandra Bussin has been consulted and concurs with the proposal to install speed bumps in this public lane.

CONTACT

Sandra Burk, Co-ordinator, Transportation Services
Toronto and East York District
Phone: (416) 392-8750
Fax: (416) 392-1920
E-mail: sburk@toronto.ca

SIGNATURE

Andrew Koropeski, P.Eng
Director, Transportation Services
Toronto and East York District

ATTACHMENTS

Drawing No. 421F-8560 dated September 2006
P:\2007\Cluster B\TRA\Toronto and East York\top\Ts07035tey.top.doc