



## Toronto Police Service

40 College Street, Toronto, Ontario, Canada. M5G 2J3  
(416) 808-2222 FAX (416) 808-8202  
Website: www.TorontoPolice.on.ca



William Blair  
Chief of Police

File Number: .....

D14#2007.08.61

September 21, 2007

Stephen Brown  
Traffic Engineer/Planner  
Toronto and East York District, West  
Metro Hall, 17<sup>th</sup> Floor  
55 John Street  
Toronto, Ontario M5V 3C6

Dear Mr. Brown:

Re: Hickson Street, between St. Clarens Avenue and Brock Avenue – Request to conduct a poll for the installation of speed humps

I forwarded your correspondence regarding the installation of speed humps on Hickson Street, between St. Clarens Avenue and Brock Avenue to Sergeant R. Sorgo (4690) 14 Division Traffic, for his assessment and feedback.

After a careful review of the data collected, both Sergeant Sorgo and I concur that the installation of speed humps are not required along this section of Hickson Street.

Further, it is believed that the installation of speed humps along this section of Hickson Street would adversely affect the abilities of emergency service vehicles such as fire and ambulance to respond to calls in a timely and safe manner.

Sincerely,

Ruth White  
Superintendent  
14 Division

RW/bam