


Attachment # 1

THE DONWAY EAST

East


Lawrence Avenue

THE DONWAY WEST



Width determined by height



Signs #1
Scale: 1/4" = 1'-0"




DETAIL SECTION
Scale: 1/2" = 1'-0"

Signs #1 & #2
Note: Exact installation details, location and dimensions to be confirmed on site.

Sign #2



Scale: NTS.



SITE DEVELOPMENT PLAN
Scale: NTS.



HOK CANADA




Donway & Lawrence Ave., North York, ON
New CIBC Signage - Site Plan & Graphic Detail Drawings
Tr# 00131 - July 23, 2007 - Page 3



WEST ELEVATION

Scale: 1/8" = 1'-0"

Note:
All lamping described are recommendations only. All sign vendors are expected to provide costing based on lamping as per stipulations listed in the accompanying specification, General Requirements.



HOK CANADA




Donway and Lawrence Ave., North York, ON
New CIBC Signage - Exterior West Elevation
TR# 00132 - July 23, 2007 - Page 1

Attachment # 4

EXISTING
ILLUMINATED BOX SIGN

EXISTING
ILLUMINATED BOX SIGN

SIGN #1
ILLUMINATED BOX SIGN
8'11" H x 8'10" W +/- Width determined by height
Proposed



Donway & Lawrence Ave., North York, ON
New CIBC Signage - Exterior South Elevation
Tr# 00132 - July 23, 2007 - Page 2



21 Melinda Street
Commerce Court East
Toronto, ON
M5V 3C9

April 2nd, 2008

Ms. Joanne Battaglia
Zoning Examiner
City of Toronto
Toronto Building North District

Dear Ms. Battaglia:

CIBC opened a new branch on April 30th, 2007 at the corner of Lawrence Ave. and the Donway. This was a result of the redevelopment of the Don Mills Shopping Centre that forced our existing location to close. The new branch represents a significant investment in the community.

CIBC takes the concerns of the community seriously. That is why I met with Mr. Terry West, President of the Don Mills Residents Inc. to discuss the group's concerns with the proposed signage. I understood the concerns raised by Mr. West and we reached a compromise suitable to both parties. We agreed to remove the imagery from the proposal but leave a square logo sign over the door and add a non-illuminated sign band on the west façade.

The additional signage is important for the following reasons:

- The logo on the south façade will help to signify the entrance of the building. On approach the entrance does not stand out visually; the logo sign will draw attention to the entrance.
- Aesthetically the logo sign will add visual weight to the south façade, which is currently somewhat blank and featureless. The sign band on the west façade will make the band effect continuous but because it will not be illuminated it should not disturb residents to the west of the branch.
- From even a small distance to the south the identification of the building as CIBC is not clear. The logo sign will greatly increase the awareness of the branch to passing motorists and pedestrians.

Your help in facilitating the approvals required for signage to be installed would be greatly appreciated.

Kind Regards,

A handwritten signature in black ink, appearing to read "M. S. Reece".

Matthew Reece
Senior Program Manager
CIBC Corporate Real Estate