

Emergency Medical Services
4330 Dufferin Street
Toronto, Ontario
Canada M3H 5R9

Tel: (416) 397-9240
Fax: (416) 392-2115
Email: bfarr@toronto.ca

January 25, 2008

Stephen C. Brown
Traffic Engineer
17th Floor, Metro Hall
Toronto, ON M5V 3C6

Re: Massey Street, between Queen Street West and Adelaide Street West-Evaluation for the Installation of Traffic Calming Devices

Dear Stephen,

We are in receipt of your letter dated December 11, 2007, regarding the request for Toronto Emergency Medical Services (EMS) position on the installation of speed bumps on Massey Street.

We recognize that this is a very sensitive issue as the citizens of Toronto feel the installation of speed bumps act as a traffic calming measure which will provide added safety to their communities.

Toronto EMS is on record as not supporting the installation of speed bumps (narrow asphalt bumps consisting of a steep vertical rise). This traffic calming measure will effect an ambulance's response time to an emergency call and subsequent transportation to the hospital. This in itself could prove detrimental to the medical conditions of some patients.

Toronto EMS supports the rights of communities that choose to install traffic calming measures (i.e. speed humps and traffic circles) for the safety of their families and neighbourhoods and will continue to work with the City and its agencies to improve public health and safety.

Yours Sincerely,

A handwritten signature in black ink that reads "B. K. Farr".

Bruce K. Farr
Chief and General Manager
Toronto Emergency Medical Services

c: Deputy Mayor Joe Pantalone