



## STAFF REPORT ACTION REQUIRED

### Prohibited Turn Regulation Housekeeping – 2911 Eglinton Avenue East, Driveway onto Landmark Boulevard

<b>Date:</b>	March 30, 2009
<b>To:</b>	Scarborough Community Council
<b>From:</b>	Acting Director, Transportation Services, Scarborough District
<b>Wards:</b>	Ward 35– Scarborough Southwest
<b>Reference Number:</b>	P:\2009\Cluster B\TRA\Scarborough\sc09023 D09-3217188 - 2911 Eglinton Landmark Blvd turn prohibitions

### SUMMARY

---

This staff report is about a matter for which the Community Council has delegated authority from City Council to make a final decision.

The purpose of this report is to advise on the need to housekeep the lack of valid by-law for the existing signage in the field.

### RECOMMENDATIONS

---

**Transportation Services, Scarborough District, recommends that Scarborough Community Council:**

1. Enact the “Prohibited Turns” Regulations as identified in Appendix 1 of this report.
2. Pass or amend the appropriate by-law(s) accordingly.

### Financial Impact

There is no financial impact associated with this report.

## **ISSUE BACKGROUND**

In the process of studying various traffic concerns on Eglinton Avenue East in the McCowan Road area, a by-law search revealed that the existing Westbound No Left-Turn and Northbound No Right-Turn signage at the driveway of 2911 Eglinton Avenue East exiting on Landmark Boulevard is not accompanied by appropriate by-laws. This driveway is physically constructed to curtail these turns.

## **COMMENTS**

In order to make the existing signage enforceable, Westbound No Left-Turn and Northbound No Right-Turn prohibitions should be enacted.

## **CONTACT**

Marko A. Oinonen, P.Eng.  
Manager, Traffic Operations, Scarborough District  
Tel: 416-396-7148  
Fax: 416-396-5641  
E-Mail: moinone@toronto.ca

## **SIGNATURE**

---

Steven T. Kodama, P.Eng.  
Acting Director, Transportation Services, Scarborough District

FJB:ca

## **ATTACHMENTS**

1. Appendix 1 – By-law Amendment (enact)
2. Location Plan (Turn Prohibitions - 2911 Eglinton Avenue East, driveway onto Landmark Boulevard)

## Appendix 1

### “Prohibited Turns” Regulation to be Enacted

(In Column 1) Intersection or Portion of Highway	(In Column 2) Direction	(In Column 3) Turns Prohibited	(In Column 4) Times or Days
Landmark Boulevard at driveway exiting from 2911 Eglinton Avenue East	Westbound	Left	Anytime
Landmark Boulevard at driveway exiting from 2911 Eglinton Avenue East	Northbound	Right	Anytime