## **DA** TORONTO Facilities Management & Real Estate Capital Program

**Budget Adjustments** Date: June 9, 2015

## Schedule "A" - 2015 Budget Adjustments

Sub-Project Name	Sub-Project (WBS No.)	Current 2015 Budget	Reductions	Revised 2015 Budget	Comment
18 Dyas Road - Facilities Management Field Offices	CCA204-02	1,569,194	(1,569,194)	-	The project to re-configure the facility to allow for field office space has been cancelled at this time.
Various Locations- Elevator machine room equipment guarding	CCA207-16	847,879	(207,000)		Non-compliant sole bidder in July 2014 resulted in re-tendering which yielded lower bids for the work. Project will be completed at the end of 2015 under budget
18 Dyas Road-Replacement of Warehouse Roof and Parking Garage Ramp	CCA209-06	248,174	(58,754)	189,420	Project will be completed under budget.
2222 Eglinton Avenue E Demolition of Free Standing building	CCA213-06	92,325	(85,000)	7,325	Project will be completed under budget.
20 Beffort-Replace Roofing Systems	CCA217-01	155,660	(35,500)	120,160	All project costs accounted for, bids came in under budget. The Project will be completed under budget
475 Dundas St. E-Replacement of Flat Roof	CCA217-02	229,660	(48,200)	181,460	All project costs accounted for, bids came in under budget. The Project will be completed under budget
40 Coronation Dr-Replace Roofing Systems	CCA217-04	223,067	(117,000)	106,067	All project costs accounted for, bids came in under budget. The Project will be completed under budget
740 Markham-Replace Roofing Systems	CCA217-05	185,000	(185,000)	-	A more thorough assessment of the roof at this site indicated that this work is no longer required. Therefore the project has been cancelled.
12 Canterbury-Replacement of Overhead Door	CCA218-07	66,000	(66,000)	-	A more thorough assessment of the roof at this site indicated that this work is no longer required. Therefore the project has been cancelled.
87 Main St-Asphalt Pavement & Air Condition Sleeping Area	CCA220-01	338,000	(171,200)	166,800	All project costs accounted for, bids came in under budget. The Project will be completed under budget
666 Renforth Dr-Asphalt Pavement Replacement Along the South Driveway & West Parking Area	CCA220-02	78,649	(37,600)	41,049	All project costs accounted for, bids came in under budget. The Project will be completed under budget
3061 Birchmount-Rpl Pavement,ConcretePaving&Curbs 256 Cosburn Ave-Replacement of Vehicle Exhaust System and Install New Garage	CCA220-04	165,916	(58,400)	107,516	All project costs accounted for, bids came in under budget. The Project will be completed under budget A more thorough assessment of the site has indicated that work planned has been completed and additional work is no longer
Ventilation System	CCA225-07	199,000	(199,000)		required. Therefore the project has been cancelled. Further SOGR work at the site have been placed on hold until
843 Eastern Ave Slab reconstruction	CCA229-13	1,520,000	(1,520,000)	-	future uses for the site are finalized.
Subtotal - Reductions		5,918,524	(4,357,848)		
Sub-Project Name	Sub-Project (WBS No.)	Current 2015 Budget	Additions	Revised 2015 Budget	Comment
5700 Bathurst St. (EMS Station 16) - Elevator Modernization	CCA219-13	134,000	254,000	388,000	Project planned to modernize the elevators and will make them compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project.
	CCA219-13 CCA220-05				compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project. Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health & safety issues. Therefore, bids received for the increased scope were over allocated budget.
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers,		749,971	950,000	1,699,971	compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project. Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health & safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project. Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior	CCA220-05			1,699,971 438,000 471,000	<ul> <li>compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project.</li> <li>Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health &amp; safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project.</li> <li>Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project.</li> <li>Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation.</li> </ul>
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior finishes 5100 Yonge Street (Norht York Civic Centre) - Replacement of the Main	CCA220-05 CCA218-03	749,971 163,000	950,000 275,000	1,699,971 438,000 471,000	<ul> <li>compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project.</li> <li>Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health &amp; safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project.</li> <li>Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project.</li> <li>Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation.</li> <li>Funding is required in support of the design component of the Paving Program for 19 sites</li> </ul>
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior finishes 5100 Yonge Street (Norht York Civic Centre) - Replacement of the Main Switchgear	CCA220-05 CCA218-03 CCA225-13	749,971 163,000	950,000 275,000 322,000	1,699,971 438,000 471,000 936,234 365,428	<ul> <li>compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project.</li> <li>Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health &amp; safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project.</li> <li>Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project.</li> <li>Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation.</li> <li>Funding is required in support of the design component of the Paving Program for 19 sites</li> <li>Funding is required in support of the design component of the Roofing Program for 18 sites</li> </ul>
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior finishes 5100 Yonge Street (Norht York Civic Centre) - Replacement of the Main Switchgear Paving - Various Locations	CCA220-05 CCA218-03 CCA225-13 New	749,971 163,000	950,000 275,000 322,000 936,234	1,699,971 438,000 471,000 936,234 365,428	compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project. Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health & safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project. Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project. Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation. Funding is required in support of the design component of the Paving Program for 19 sites Funding is required in support of the design component of the Roofing Program for 18 sites Funding is required in support of the design component of the Structural Program at 4 sites
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior finishes 5100 Yonge Street (Norht York Civic Centre) - Replacement of the Main Switchgear Paving - Various Locations Roofing - Various Locations	CCA220-05 CCA218-03 CCA225-13 New New	749,971 163,000 149,000 - -	950,000 275,000 322,000 936,234 365,428	1,699,971 438,000 471,000 936,234 365,428 61,371	compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project. Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health & safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project. Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project. Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation. Funding is required in support of the design component of the Paving Program for 19 sites Funding is required in support of the design component of the Roofing Program for 18 sites Funding is required in support of the design component of the Structural Program at 4 sites Funding is required in support of the design component of the Building Envelope Program at 16 sites
Elevator Modernization 850 Coxwell (East York Civic Centre) - Replacement of exterior pavers, curbs and finishes and expansion of steps, pavers, foundations and hard and soft landscaping 259 Horner Ave. (EMS Station 38) - Replace windows, doors, misc. interior finishes 5100 Yonge Street (Norht York Civic Centre) - Replacement of the Main Switchgear Paving - Various Locations Roofing - Various Locations Structural - Various Locations	CCA220-05 CCA218-03 CCA225-13 New New	749,971 163,000 149,000 - -	950,000 275,000 322,000 936,234 365,428 61,371	1,699,971 438,000 471,000 936,234 365,428 61,371 896,833	compliant with current AODA legislation. Bids received exceeded funding available. Additional funds required award contract and complete the project. Flooding issues in the walkways at the site have resulted in a need for scope to include regarding, sloping and resetting catch basins to mitigate health & safety issues. Therefore, bids received for the increased scope were over allocated budget. Additional funds required to complete the project. Pre-tender estimates indicate that bids will exceed available budget. Additional funds required ensure sufficient funding is available to complete the project. Further investigation has identified a need for a temporary switchboard during the replacement of the main switchgear to ensure the power supply is not disrupted during the main replacement. Additional funding is needed for this as it was not included in the original budget. Funds are also being accelerated to fast track the implementation. Funding is required in support of the design component of the Paving Program for 19 sites Funding is required in support of the design component of the Roofing Program for 18 sites Funding is required in support of the design component of the Structural Program at 4 sites Funding is required in support of the design component of the

FMRE Capital Budget Adjustments (Q2 2015) - Schedule A - 2015 Budget Adjustments