

## STAFF REPORT **ACTION REQUIRED**

# Standing Prohibition - Commissioners Street

Date:	December 5, 2014
To:	Toronto and East York Community Council
From:	Director, Transportation Services, Toronto and East York District
Wards:	Toronto-Danforth, Ward 30
Reference Number:	Ts2014190te.top.doc

## SUMMARY

Transportation Services is seeking authority from City Council to prohibit standing on the north side of Commissioner Street, between a point 186 metres east of Carlaw Avenue and a point 15 metres further east. The prohibition will enhance sight lines for drivers exiting the Toronto Hydro parking garage driveway, it will however result in the loss of one parking space.

## RECOMMENDATIONS

## **Transportation Services recommends that:**

1. City Council prohibit standing on the north side of Commissioners Street between a point 186 metres east of Carlaw Avenue and a point 15 metres further east.

## **Financial Impact**

Funding for the installation of standing prohibition signs in the estimated amount of \$500.00 is available within the Transportation Services 2015 Interim Operating Budget.

#### ISSUE BACKGROUND

Transportation Services, in consultation with Councillor Paula Fletcher, investigated a request from Toronto Hydro to enhance sight lines on Commissioners Street at the driveway exit for their parking garage.

### COMMENTS

Commissioners Street is a four-lane 21 metre wide collector road operating two-way between Cherry Street and Leslie Street. Parking is generally allowed on both sides of the street for a maximum period of three-hours. The TTC operates a bus service along Commissioners Street.

The driveway to the Toronto Hydro parking garage at No. 500 Commissioners Street intersects with the north side of Commissioners Street. When a vehicle is parked on the north side of the street immediately east of the driveway, sight lines for motorists exiting the driveway are obstructed. As a result, a driver must encroach into westbound traffic, creating a potentially hazardous situation. Westbound motorists on Commissioners Street also have reduced visibility of vehicles exiting the driveway.

To improve sight lines and enhance safety, a standing prohibition could be implemented on the north side of Commissioners Street, between the driveway and a point five metres east. This would result in the loss of one on-street parking space.

## CONTACT

Brian Holditch, Transportation Technologist Traffic Operations, Toronto and East York District Phone (416) 338-5428

Fax: (416) 392-1920

e-mail: bholditc@toronto.ca

## SIGNATURE

Kyp Periklous Director, Transportation Services Toronto and East York District

## LIST OF ATTACHMENTS

(1) Drawing No. 421G-1614, dated December 2014