



STAFF REPORT ACTION REQUIRED

Proposed Relocation of Speed Bump – First East-West Public Lane North of Queen Street West, Between Northcote Avenue and Beaconsfield Avenue

Date:	October 30, 2013
To:	Toronto and East York Community Council
From:	Director, Transportation Services, Toronto and East York District
Wards:	Davenport, Ward 18
Reference Number:	Ts2013211te.top.doc

SUMMARY

This staff report is about a matter for which Toronto and East York Community Council has delegated authority from City Council to make a final decision.

Transportation Services is requesting approval from Toronto and East York Community Council to relocate one speed bump in the first east-west public lane north of Queen Street West, between Northcote Avenue and Beaconsfield Avenue.

RECOMMENDATION

Transportation Services recommends that Toronto and East York Community Council:

1. Approve the relocation of one speed bump in the first east-west public lane north of Queen Street West, between Northcote Avenue and Beaconsfield Avenue, as shown on Drawing No. 421G-1202 dated September 2013, attached to the report dated September 26, 2013 from the Director, Transportation Services, Toronto and East York District.

Financial Impact

Funding to undertake the signage and speed bump adjustments in the estimated amount of \$500.00 is available within the Transportation Services Division's Capital budget laneways account CTP 313-05.

ISSUE BACKGROUND

The former City of Toronto Council, at its meeting held on August 14, 1995, adopted Clause No. 29 of City Services Committee Report No. 11, which contained a recommendation that speed bumps be installed in the public lane system first north of Queen Street West, from Dovercourt Road to Gladstone Avenue. By-law No. 536-1995 was enacted in connection with this Clause.

Councillor Bailão, on behalf of area residents, recently requested that Transportation Services staff investigate and report on the feasibility of relocating the easternmost speed bump in the east-west section of public lane north of Queen Street West, between Northcote Avenue and Beaconsfield Avenue.

COMMENTS

Transportation Services has no objection to relocating the speed bump at this location. The proposed speed bump relocation is shown on the attached Drawing No. 421G-1202 dated September 2013.

CONTACT

Sandra Burk
Supervisor, Transportation By-laws
Telephone: 416-392-8750
Email: sburk@toronto.ca

SIGNATURE

Jacqueline White, P. Eng.
Director, Transportation Services
Toronto and East York District

ATTACHMENT

Drawing No. 421G-1202, dated September 2013

P:\2013\Cluster B\TRA\Toronto and East York District\TOP\Ts2013211te.top.doc – bmk