



STAFF REPORT ACTION REQUIRED

No Stopping Anytime – 225 Davenport Road

| | |
|--------------------------|---|
| Date: | May 12, 2015 |
| To: | Toronto and East York Community Council |
| From: | Director, Transportation Services, Toronto and East York District |
| Wards: | Toronto Centre–Rosedale, Ward 27 |
| Reference Number: | Ts2015073te.top.doc |

SUMMARY

Transportation Services is requesting approval from City Council to implement a "No Stopping Anytime" parking regulation adjacent to the driveway that services 225 Davenport Road (Dakota Condominium Complex) in order to deter parking and improve site-lines for all road users exiting this driveway.

RECOMMENDATIONS

Transportation Services recommends that:

1. City Council prohibit stopping at all times, on the south side of Davenport Road, from a point 88 metres east of Avenue Road to a point 22 metres further east;
2. City Council rescind the existing "No Parking from 7:30 a.m. to 9:30 a.m., Monday to Friday except public holidays" regulation, on the north/east side of Davenport Road, between Dupont Street and Yonge Street;
3. City Council rescind the existing "No Parking from 3:30 p.m. to 6:30 p.m., Monday to Friday except public holidays" regulation, on the south/west side of Davenport Road, between Dupont Street and Yonge Street;
4. City Council rescind the existing "No Stopping from 3:30 p.m. to 6:30 p.m., Monday to Friday except public holidays" regulation, on the north/east side of Davenport Road, between Dupont Street and Yonge Street;
5. City Council rescind the existing "No Stopping from 7:30 a.m. to 9:30 a.m., Monday to Friday except public holidays" regulation, on the south/west side of Davenport Road, between Dupont Street and Yonge Street;

6. City Council rescind the existing " 1 hour 8:00 a.m. to 6:00 p.m., Monday to Saturday" regulation, on the north and east side of Davenport Road, between Bedford Road and Bay Street;
7. City Council rescind the existing " 2 hour 8:00 a.m. to 6:00 p.m., Monday to Saturday" regulation, on the north and east side of Davenport Road, between Bedford Road and Dupont Street; and
8. City Council rescind the existing " 1 hour 8:00 a.m. to 6:00 p.m., Monday to Saturday" regulation, on the south side of Davenport Road, between Bay Street and Bedford Road.

Financial Impact

Funding to undertake the signage adjustments in the estimated amount of \$500.00 is available within the Transportation Services 2015 Operating Budget.

ISSUE BACKGROUND

At the request of Councillor Kristyn Wong-Tam, on behalf of area residents, Transportation Services reviewed the feasibility of implementing a no stopping regulation fronting a condominium complex to address sight-line issues.

COMMENTS

Davenport Road is classified as a major arterial roadway operating two-way, eastbound and westbound, with a pavement width of 19 metres, and a posted limit of 40 km/h. TTC No. 6 Bay bus service operates on this section of Davenport Road. The Dakota Condominium Complex, 225 Davenport Road, is located on the south side of Davenport Road, east of Avenue Road. The driveway that services this building, is also located on Davenport Road.

Pay parking operates from 8:00 a.m. to 9:00 p.m., Monday to Saturday, and 1:00 p.m. to 9:00 p.m., Sunday. Otherwise parking is allowed for a maximum period of three hours.

The Dakota Condominium Complex has requested Transportation Services to review the feasibility of prohibiting stopping at all times on the west and east side of the driveway, that services this building, in order to improve site-lines for all road users.

The proposed stopping regulation for Davenport Road is shown in the attached Drawing No. 421G- 1749, dated April 2015. This no stopping proposal should help deter parking in the vicinity of the driveway and improve site-lines for all road users. No on-street parking spaces will be eliminated as a result of this recommendation.

During the course of our investigation it was also noted that there are discrepancies, between the posted signs and the parking regulation by-laws. The recommendations in this report will correct these discrepancies, specifically, Recommendations No. 2 through 8.

CONTACT

Ann S. Khan, P.Eng.
Manager, Traffic Operations
Toronto and East York District
Telephone: 416-397-5021
Fax: 416-392-1920
e-mail: akhan5@toronto.ca

SIGNATURE

Kyp Perikleous
Director, Transportation Services
Toronto and East York District

LIST OF ATTACHMENTS

(1) Drawing No. 421G- 1749, dated April 2015

P:\2015\Cluster B\Tra\Toronto and East York\Top\Ts2015073te.top.doc - acb