



February 16, 2022

Toronto and East York Community Council
100 Queen Street West
Toronto ON M5H 2N2

Dear Chair and Council Members,

RE: Updating Signage to Ensure Pedestrian and Public Safety on Reverend Porter Lane

Reverend Porter lane is a one way northbound lane, from Carleton Street to Wood Street.

Pedestrians using the sidewalk along Wood Street are constantly at risk of being hit by a vehicle exiting Reverend Porter Lane due to a lack of safety features for both motorists and pedestrians at the mouth of the lane's exit on Wood Street.

My office has consulted with Transportation Staff about the feasibility of adding new road safety features. The installation of these mechanisms will improve pedestrian safety along this stretch of Wood Street.

Recommendations:

1. Toronto and East York Community Council authorize the installation of speed bumps in Reverend Porter Lane, between Carlton Street and Wood Street, at the locations shown on Drawing 421G-3987, dated January 2022, from the Director, Traffic Management, Transportation Services, Toronto and East York District.
2. Toronto and East York Community Council authorize a compulsory stop control for northbound traffic on Reverend Porter Lane at Wood Street.

Respectfully submitted,

Councillor Kristyn Wong-Tam
Ward 13, Toronto Centre

