



PB21.1

41-45 Spadina Road - Alteration to Attributes of a Designated Heritage Property under Section 33 of the Ontario Heritage Act and Authority to Enter into a Heritage Easement Agreement

PB21.1 41-45 Spadina Road



This location map is for information purposes only; the exact boundaries of the property are not shown. The arrow marks the location of the site.

PB21.1
41-45 Spadina Road



Aerial View

PB21.1
41-45 Spadina Road




Front/West Elevation at Spadina Road

PB21.1
41-45 Spadina Road




North Elevation at Lowther Avenue with North Rear Elevation in View

PB21.1 41 – 45 Spadina Road



Structural Columns – at South and in Courtyard - Infill lobby at courtyard results in removal of two rear windows

PB21.1 41-45 Spadina Road



Alterations – Removal of two courtyard windows and combining two bedrooms at Unit 9.

PB21.1
41-45 Spadina Road

