

Traffic Calming (Speed Humps) - Van Allan Road

Date: June 25, 2024

To: Scarborough Community Council

From: Director, Traffic Management, Transportation Services

Wards: Ward 24, Scarborough-Guildwood

SUMMARY

This staff report is about a matter that Community Council has delegated authority from City Council to make a final decision.

Transportation Services is recommending the installation of speed humps on Van Allan Road, between Confederation Drive and Steenvale Drive. Staff's assessment indicates that the criteria as set out in the updated Traffic Calming Policy has been satisfied. Therefore, speed humps should be installed on Van Allen Road.

RECOMMENDATIONS

The Director, Traffic Management, Transportation Services recommends that:

1. Scarborough Community Council authorize the installation of speed humps on Van Allan Road, between Confederation Drive and Steenvale Drive.
2. Scarborough Community Council direct the City Solicitor to prepare a by-law to alter the roadway for the installation of two speed humps on Van Allan Road, between Confederation Drive and Steenvale Drive, generally as shown on Attachment 2, Drawing No. TC-288 dated May 2024, attached to the report entitled "Traffic Calming (Speed Humps) - Van Allan Road" from the Director, Traffic Management, Transportation Services.
3. Subject to approval of Recommendations 1 and 2 above, Scarborough Community Council reduce the speed limit from 50 km/h to 30 km/h on Van Allan Road, between Confederation Drive and Steenvale Drive, in conjunction with the installation of speed humps.

FINANCIAL IMPACT

The estimated cost for installing two speed humps on Van Allen Road is \$8,000.00. Funding would be subject to availability and competing priorities within the Transportation Services 2025 Capital Budget.

DECISION HISTORY

This report addresses a new initiative.

COMMENTS

Transportation Services received a request from the Ward Councillor, on behalf of area residents, to investigate the feasibility of installing speed humps on Van Allan Road, between Confederation Drive and Steenvale Drive. The residents are concerned that motorists travel at a high rate of speed on Van Allan Road.

Existing Conditions

Van Allan Road is characterized by the following conditions:

- It is a two-lane, east-west, local roadway
- It operates two-way traffic on a pavement width of approximately 8.5 metres
- The daily two-way traffic volume is approximately 450 vehicles
- The speed limit is 50 km/h. Transportation Services advises that the speed limit is planned to be reduced to 30 km/h on this street by 2026+, consistent with Item 2019.IE6.8 (Vision Zero 2.0 – Road Safety Plan Update).
- Heavy trucks are prohibited at all times
- There is no Toronto Transit Commission (TTC) service provided
- There are sidewalks located on both sides of the street

The land use in the area consists of detached and semi detached residential dwellings. This subject section of Van Allan Road is not within a designated Community Safety Zone.

A map of the area and proposed locations of the speed humps is included in Attachment 2.

Study Results

As part of the assessment of the warrant criteria, a three-day speed and volume study was conducted on Van Allan Road from March 19 to 21, 2024.

The study results on Van Allan Road disclosed the following:

- 24-hour total vehicle volume is 467 vehicles
- The block length from Confederation Drive and Steenvale Drive is 180 metres
- The operating speed, which is the speed at which 85 percent of traffic is travelling at or below, was observed at 38 km/h
- The 95th percentile speed, which is the speed at which 95 percent of traffic is travelling at or below, was observed at 41 km/h

Based on the study results, Van Allan Road has satisfied the warrant criteria for both minimum block length and minimum vehicle speed. The block length was greater than 120 metres and the operating speed is 8 km/h over the warranted speed of 30 km/h.

The overall investigation concluded that the eligibility and warrant criteria outlined in the updated Traffic Calming Policy have been satisfied. Therefore, staff recommend the installation of speed humps on Van Allan Road.

Relative Priority and Other Impacts

In the event that the number of approved requests for roadway traffic calming measures exceeds the budget allocated for installation, funding for approved installations will be prioritized using a Prioritization Score. This score is made up of a Quantitative Score and a Qualitative Score.

The Quantitative Score is based on the results of the data collection, including travel speeds and traffic volumes to prioritize locations with higher vehicle speeds and volumes.

The Qualitative Score includes:

- Collision history to prioritize locations with a history of serious injury or fatal collisions and those involving a pedestrian or cyclist
- Equity to prioritize equity-deserving communities with a high-concentration of priority populations and those that are transportation disadvantaged
- Expected presence of vulnerable road users (elderly population, school children and pedestrians, including transit riders) to prioritize locations with a higher risk of fatal and serious injury collisions

The Quantitative and Qualitative Scores are averaged to provide the complete Prioritization Score. Van Allan Road, between Confederation Drive and Steenvale Drive, scored 41 ranking points out of a possible 100.

No alterations to parking regulations will be required, nor will the number of parking spaces be affected by the installation of speed humps. Installation of speed humps will have minimal effect on winter services, street cleaning and garbage collection.

Consultation with emergency services (Toronto Police Service, Toronto Fire Services and Toronto Paramedic Services) is required to ensure that the design and layout of a traffic calming proposal does not unduly affect their operations. Emergency services were advised of this proposal.

Toronto Fire Services responded and advised of potential delays in emergency responses but expressed support for initiatives that enhance community safety. A copy of their full response is included in Attachment 3. Toronto Paramedic Services have also provided their comments. A copy of their full response is included in Attachment 4. Toronto Police Service has not provided comments back at the time of writing this report. Installing speed humps will result in slower operating speeds for all vehicles, including emergency service vehicles.

The Ward Councillor has been advised of the recommendations in this report.

CONTACT

Dan Clement, CET, Manager Traffic Operations (Area 1), Transportation Services
416-397-5021, Dan.Clement@toronto.ca

SIGNATURE

Roger Browne, M.A.Sc., P. Eng.
Director, Traffic Management, Transportation Services

ATTACHMENTS

Attachment 1: Traffic Calming Warrant - Van Allan Road, between Confederation Drive and Steenvale Drive

Attachment 2: Speed Hump Locations Plan - Van Allan Road - TC-288


Attachment 3: Letter from Toronto Fire Services, dated April 23, 2024

Attachment 4: Letter from Toronto Paramedic Services, dated April 25, 2024

Attachment 1: Traffic Calming Warrant - Van Allan Road, between Confederation Drive and Steenvale Drive

Criteria		Requirement	Warrant Satisfied?
Community Support		A direct request from the Ward Councillor OR identified by Transportation Services in consultation with the Ward Councillor	Yes
Eligibility Criteria	Road Classification	Classified as a local or collector roadway, according to the Toronto Road Classification System	Yes
	Sidewalks	Presence of a sidewalk on at least one side of a local roadway and both sides of a collector roadway is preferred but not required	Yes
	Traffic Volume	Maximum average daily traffic volume of less than 8,000 vehicles per day	Yes
	Road Grade	Maximum roadway grade of up to 5%, can be considered in locations where the road grade is between 5% and 8% with additional review	Yes
	Emergency Services	No significant impacts on emergency services, including Toronto Fire, Paramedic and Police Services	No
	Transit Services	No significant impacts to regularly scheduled Toronto Transit Commission (TTC) services	N/A
Warrant Criteria	Minimum Block Length	Minimum block length of 120 metres based on the measured distance from centre to centre of controlled intersections AND	Yes (180 m)
	85th percentile speed	Minimum 85th percentile speed of 8 km/h over the warranted speed limit OR	Yes (38 km/h)
	95th percentile speed	Minimum 95th percentile speed of 15 km/h over the warranted speed limit	No (41 km/h)

Attachment 2: Speed Hump Locations Plan - Van Allan Road - TC-288



Attachment 3: Letter from Toronto Fire Services, dated April 23, 2024



Matthew Pegg
Fire Chief and General Manager

Paul Raftis
Deputy City Manager
Community & Social Services

Fire Services
4330 Dufferin Street
Toronto, Ontario M3H 5R9

Email: OfficeoftheFireChief@toronto.ca

April 23, 2024

Omar Omar
Engineering Technologist Tech 1
City Of Toronto | Transportation Services,
Traffic Operations – Area 1D
Scarborough Civic Centre, 2nd [Floor](#)

**RE: Location (Van Allan Road between Confederation Drive and [Steventale Drive](#))
Speed Hump Investigative Summary**

We are in receipt of and have reviewed the proposal for installation of traffic calming measures (speed humps) on Location (**Van Allan Road between Confederation Drive and [Steventale Drive](#)**) and provide the following comments.

Toronto Fire Services does not support this proposed speed hump installation as it may negatively impact service delivery. The physical restrictions imposed by speed humps have a greater impact on fire vehicles. Response time increases with every obstacle encountered responding to any emergency incident and the cumulative impact of several speed humps can increase responses times.

Toronto Fire Services is supportive of initiatives that improve safety for all citizens of and visitors to the City of Toronto. However, careful consideration must be given to accepting a delay to emergency response vehicles as a compromise to combat the risks presented by all vehicular traffic. Our recommendation is that non-physical measures be considered and evaluated to determine if desired results can be obtained without imposing a physical obstacle to emergency vehicles.

Regards,

Claudio Gloazzo
Acting District Chief
Emergency Planning
Toronto Fire Services
City of Toronto
O-416-338-7708
C-416-688-0114



Attachment 4: Letter from Toronto Paramedic Services, dated April 25, 2024

From: [Atif Sharif](#)
To: [Omar Omar](#); [Councillor Ainslie CO](#); [Jennifer Paredes](#)
Cc: [Geena Yadav](#); [Meri Newton](#); ["Trafficservices@torontopolice.on.ca"](mailto:Trafficservices@torontopolice.on.ca); [Joseph Del Vasto](#); [Claudio Gloazzo](#)
Subject: RE: Speed humps - Van Allan Road between Confederation Drive and Steenvale Drive
Date: April 25, 2024 12:29:16 PM
Attachments: [image002.png](#)
[image003.png](#)

Good afternoon Omar,

We have received and reviewed the proposal for installation of speed humps on Van Allan Road between Confederation Drive and Steenvale Drive, with the following comments:

Van Allan Road appears to primarily service the residents that reside on the roadway and would not impact response times for other community members. It is important that the applicant understand that the installation of traffic calming devices will reduce the speed that emergency vehicles travel when responding to emergencies on roadways where they are installed.

Toronto Paramedic Services is supportive of community initiatives that improve the safety of all citizens of, and visitors to, the City of Toronto. Traffic and pedestrian safety are key components of a healthy neighbourhood, and we endeavour to support the wishes of the community to implement measures to improve upon these components.

Many Thanks,

Atif Sharif
A/Commander - Policy, Projects & Process Improvement
Office of the Chief
Toronto Paramedic Services
Tel: 416-397-7493

