

Revised Speed Bump Locations - Public Lane west of Logan Avenue, north of Colgate Avenue

Date: March 18, 2025

To: Toronto and East York Community

From: Director, Traffic Management, Transportation Services

Wards: Ward 14, Toronto-Danforth

SUMMARY

This staff report is about a matter that Community Council has delegated authority from City Council to make a final decision.

Transportation Services is recommending revised speed bump locations in the public lane west of Logan Avenue, north of Colgate Avenue, due to concerns with garage access and signage resulting from the initial layout that was approved by Toronto and East York Community Council in 2024. The updated plan minimizes impacts while maintaining effective traffic calming and preserving the intent of the original proposal.

RECOMMENDATIONS

The Director, Traffic Management, Transportation Services recommends that:

1. Toronto and East York Community Council amend its previous decision on Item TE12.55 by replacing Drawing TC-236 in Attachment 1 to the report entitled "Speed Bumps - Public Lane west of Logan Avenue, north of Colgate Avenue", dated March 14, 2024, from the Director, Traffic Management, Transportation Services, with Drawing TC-464, dated March 2025 in Attachment 1 to the report entitled "Revised Speed Bumps Locations - Public Lane west of Logan Avenue, north of Colgate Avenue", from the Director, Traffic Management, Transportation Services.

FINANCIAL IMPACT

There are no additional costs associated with the proposed amendment.

DECISION HISTORY

On April 3, 2024, Toronto and East York Community Council adopted Item TE12.55 entitled "Speed Bumps - Public Lane west of Logan Avenue, north of Colgate Avenue", authorizing the installation of speed bumps on the public laneway west of Logan Avenue, north of Colgate Avenue. The decision can be found at:

[Agenda Item History - 2024.TE12.55](#)

COMMENTS

In response to challenges that have arisen from the installation of speed bumps and signage that were approved through the original report in 2024, staff have revised the previously submitted speed bump locations plan to address concerns about both vehicle access to garages and the need for additional signage. The updated plan minimizes these impacts while maintaining effective traffic calming by strategically placing bumps and utilizing existing utility poles for signage where possible. This adjustment ensures a more practical and balanced implementation while preserving the intent of the original proposal.

The Ward Councillor has been advised of the recommendation in this report.

CONTACT

Dan Clement, CET, Manager Traffic Operations (Area 1), Transportation Services
416-397-5021, Dan.Clement@toronto.ca

SIGNATURE



for

Roger Browne, M.A.Sc., P. Eng.
Director, Traffic Management, Transportation Services

ATTACHMENTS

Attachment 1: Map - Speed Bumps Locations Plan - Lane west of Logan Avenue, north of Colgate Avenue, Colgate Avenue - Paisley Avenue

Attachment 1: Map - Speed Bumps Locations Plan - Lane west of Logan Avenue, north of Colgate Avenue, Colgate Avenue - Paisley Avenue

