


## **SERVICE CONNECTIONS**



## NOTES:

- 1. CATHODIC PROTECTION NOT REQUIRED ON FITTINGS CONNECTED TO METALLIC MAIN.
- 2. ALL EXPOSED THERMITE WELDS MUST BE PROTECTED WITH A THICK COAT OF MASTIC.

<b>UII IORONTO</b> Engineering Service			ces - Works Facilities & Structures
SCALE:	1:100	CATHODIC PROTECTION FOR VALVES NOT IN CHAMBER IRON FITTINGS, HYDRANT & SERVICE CONNECTION ON NON-METALLIC MAINS	DRAWING NUMBER:
DATE:	JANUARY 2008		T-1106.04
DRAFTING:	N.AGIC		SHEET: 1 of 1

**TECHNICAL SERVICES**