

Superseded/Cancelled (Remove)		Revised/New (Insert)		Drawings for Sewers and Watermains
T No.	Revision	T No.	Revision	Remarks
All T-drawings				Revision numbers: - Revision No. 0 means original release. - Revision No. 1 means first revision. - Revision No. 2 means second revision Revision No. 3 means third revision and so on.
---	--	T-705.011 Sep 2025	0	Offset Catchbasin with Sump New drawing.
T-1110.08-1 Sep 2021	1	T-1110.08-1 Sep 2025	2	750 mm Horizontal Butterfly Valve Chamber (Position A) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.08-2 Sep 2021	1	T-1110.08-2 Sep 2025	2	750 mm Horizontal Butterfly Valve Chamber (Position B) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.09-1 Sep 2021	1	T-1110.09-1 Sep 2025	2	900 mm Horizontal Butterfly Valve Chamber (Position A) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.09-2 Sep 2021	1	T-1110.09-2 Sep 2025	2	900 mm Horizontal Butterfly Valve Chamber (Position B) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.10-1 Sep 2021	1	T-1110.10-1 Sep 2025	2	1050 mm Horizontal Butterfly Valve Chamber (Position A) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.10-2 Sep 2021	1	T-1110.10-2 Sep 2025	2	1050 mm Horizontal Butterfly Valve Chamber (Position B) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.11-1 Sep 2021	1	T-1110.11-1 Sep 2025	2	1200 mm Horizontal Butterfly Valve Chamber (Position A) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.11-2 Sep 2021	1	T-1110.11-2 Sep 2025	2	1200 mm Horizontal Butterfly Valve Chamber (Position B) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.
T-1110.12-1 Sep 2021	1	T-1110.12-1 Sep 2025	2	1350 mm Horizontal Butterfly Valve Chamber (Position A) Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.

Superseded/Cancelled (Remove)		Revised/New (Insert)		Drawings for Sewers and Watermains
T-1110.12-2 Sep 2021	1	T-1110.12-2 2Sep 2025	2	1350 mm Horizontal Butterfly Valve Chamber (Position B) • Mark C44 – Revise Victaulic Coupling from Style 44 to Style W77.