



Window Security Bars Demonstration of a Reinstallation		Exterior Condition Assessment		10 St. Mary St., Suite 801 Toronto, Canada, M4Y 1P9 416 963.4497 T 416 963.8761 F		E.R.A.	
This drawing is the property of E.R.A Architect Inc. and may not be used or reproduced without expressed approval.	No.	Date:	Issued For:	Scale:	As Shown	Date:	20 May 2008
	01	May 2008	Bldg Condition Report	Drawn by:	RH	Sheet No:	SK-1
The Contractor shall verify all levels and dimensions on site and report all discrepancies to E.R.A. before beginning work.				Reviewed by:	AP		
Do not scale the drawings. Use figured dimensions only. The Contractor shall be responsible for any changes made to the drawings without E.R.A.'s approval.				Project No.:	03-092-02		
				prepared for : Bridgepoint Health 14 St. Matthews Road			