

**MUNICIPAL LICENSING AND  
STANDARDS DIVISION  
SIGN INVESTIGATIONS LIST  
NORTH YORK DISTRICT  
MARCH 7, 2008**

Property Address	Ward	# of Signs	Complaint	Violation Notice	Charges Initiated	Status
1640 Avenue Rd	16	2	Double- sided 3rd party 10 x 35 roof sign. Permit #S98-04956. Installed 10 x 40 signs.			Active Investigation
1798 Avenue Rd	16	4	Two -double- sided 3rd party 10 x 35 roof sign, one facing north & one facing south. Permit # 00-158984. Installed 10 x 40 signs.			Active Investigation
3747 Bathurst St	10	2	Side by side 3rd party 10 x 35 roof sign. Permit # S95-015646. Installed 10 x 40 signs.			Active Investigation
3768 Bathurst St	10	2	Double- sided 3rd party 10 x 35 roof sign Permit # 04-118012. Installed 10 x 40 signs.			Active Investigation
3818 Bathurst St	10	2	Double- sided 3rd party 10 x 40 roof sign. No permits found.			Active Investigation
4929 Bathurst St	10	2	Double- sided 3rd party 10 x 40 roof sign. No permits found.			Active Investigation
4899 Bathurst St	10	2	Double- sided 3rd party 10 x 35 roof sign at 30 degree split . Permit # 04-150426. Installed 10 x 40 signs.			Active Investigation
3181 Bathurst St	16	2	Double- sided 3rd party 10 x 35 roof sign. Permit # S99-03199. Installed 10 x 40 signs.			Active Investigation
3321 Bathurst St	16	2	Double- sided 3rd party 10 x 35 roof sign Permit # 00-333215. Installed 10 x 40 signs.			Active Investigation
3437 Bathurst St	16	2	Double- sided 3rd party 10 x 35 roof sign. Permit # S8808986. Installed 10 x 40 signs.			Active Investigation
3546 Bathurst St	16	2	Double- sided 3rd party 10 x 35 roof sign. Permit # 00-153182. Installed 10 x 40 signs.			Active Investigation
100 Bridgeland Av	15	2	Double-sided 10x40 third party ground sign. Only first party signs are permitted.			Active Investigation
302 Bridgeland Av	15	2	First party double-sided roof sign, permit #06-187516. Installed 3rd party sign within MTO jurisdiction. Permit cancelled.			Active Investigation
1277 Caledonia Rd	15	2	Double- sided 3rd party 10 x 35 roof sign. Permit # S9903826. Installed 10 x 40 signs.			Active Investigation
3590 Dufferin St	9	2	Double- sided 3rd party 10 x 405 roof sign			Active Investigation
2434 Dufferin St	15	1	Vinyl Fascia sign without a permit			Active Investigation
2931 Dufferin St	15	2	Double- sided 3rd party 10 x 405 roof sign			Active Investigation
943 Eglinton Av E	26	1	3rd party roof sign where no 3rd party signs are permitted			Active Investigation
953 Eglinton Av E	26	1	3rd party roof sign where no 3rd party signs are permitted			Active Investigation
135 Fenelon Dr	34	1	3rd party wall sign where no 3rd party signs are permitted			Active Investigation
600 Finch Av W	10	1	V-shaped ground sign with a sign area of 10 feet by 20 feet. Proposed sign will have a height of 25 feet above the adjacent grade.			Active Investigation
2133 Jane St	9	2	3rd party roof sign are not back to back and are visible from 401			Active Investigation
491 Lawrence Av W	16	1	Fascia sign without a permit			Active Investigation
788 Marlee Av	15	1	Single- sided 3rd party 10 x 35 roof sign. Permit # 04-146275. Installed 10 x 40 signs.			Active Investigation
1880 O'Connor Dr	34	2	Double-sided 10x 40 3rd party roof sign			Active Investigation
Railway Land			Railway Land South of Eglinton East of Leslie By-law 211-79 prohibits 3rd party signs in the area			Active Investigation
Railway Land			Railway Land North of Lawrence East West of Canforth Rd. By-law 211-79 prohibits 3rd party signs in the area			Active Investigation
850 Sheppard Av E	24	2	Double-sided 10x 40 3rd party roof sign			Active Investigation
1492 Victoria Pk Av	34	2	Double-sided 10x 40 3rd party roof sign			Active Investigation

**MUNICIPAL LICENSING AND  
STANDARDS DIVISION  
SIGN INVESTIGATIONS LIST  
NORTH YORK DISTRICT  
MARCH 7, 2008**

<b>Property Address</b>	<b>Ward</b>	<b># of Signs</b>	<b>Complaint</b>	<b>Violation Notice</b>	<b>Charges Initiated</b>	<b>Status</b>
1752 Victoria Pk Av	34	2	Double- sided 3rd party 10 x 35 roof sign . Permit # 02-193637 & 04-153579. Installed 10 x 40 signs.			Active Investigation
1105 Wilson Av	9	2	Double- sided 3rd party 10 x 35 roof sign. Permit # 03-139701. Installed 10 x 40 signs.			Active Investigation
421 Wilson Av	10	2	Double- sided 3rd party 10 x 35 roof sign. Permit # S9800993 & 00-343584. Installed 10 x 40 signs.			Active Investigation
2454 Yonge St	16	1	Variance granted for 1st party non-illuminated mural sign whereas an illuminated mural has been installed. Permit #72-021645; 91-018713; 93-024082; 05-138589			Active Investigation
4775 Yonge St	23	4	Four faces of 3rd party 10 x 35 roof sign. Permit # 01-194141. Installed 10 x 40 signs.			Active Investigation
4910 Yonge St	23	2	Double- sided 3rd party 10 x 35 roof sign. Permit # 00-123012 & 03-158591. Installed 10 x 40 signs.			Active Investigation
5215 Yonge St	23	2	Double- sided 3rd party 10 x 35 roof sign . Permit # 00-134198. Installed 10 x 40 signs.			Active Investigation
5400 Yonge St	23	2	Double- sided 3rd party 10 x 35 roof sign. Permit # 03-116255. Installed 10 x 40 signs.			Active Investigation
5585 Yonge St	23	2	Double-sided 10x 40 3rd party roof sign			Active Investigation
5868 Yonge St	23	1	Single-sided 10x 40 3rd party roof sign			Active Investigation
5884 Yonge St	23	2	Double- sided 3rd party 10 x 35 roof sign. Permit # S95-02943 & 02-165374. Installed 10 x 40 signs.			Active Investigation
5999 Yonge St	23	2	Side by side 3rd party 10 x 35 roof sign. Permit # 01-155144. Installed 10 x 40 signs.			Active Investigation
6120 Yonge St	23	2	Double- sided 3rd party 10 x 35 roof sign. Permit 00-140593 & 02-175061. Installed 10 x 40 signs.			Active Investigation
3145 Yonge St	25	1	Fascia sign without a permit			Active Investigation
3479 Yonge St	25	1	Fascia sign without a permit			Active Investigation
185 Yorkland Blvd	33	1	Ground sign without a permit			Active Investigation