

IE10.2 Attachments 1 to 10

Attachment 1 – Man lift operating in close proximity to overhead wires



24.10.2017

Attachment 2 – Downed electrical Wires over live Traffic lanes



24.10.2017

Attachment 3 – Downed electrical wires over live traffic lanes



24.10.2017

Attachment 4 – Road closures due to downed electrical wires



24.10.2017

Attachment 5 – Machine impact to temporary concrete barrier and chain link fence



28.11.2017

Attachment 6 – Machine impact to temporary concrete barrier and chain link fence



28.11.2017

Attachment 7 – Unrestricted access to work zone and drop-off to valley below



Attachment 8 – Unrestricted Access to work zone and drop-off to valley below



Attachment 9 – Unrestricted access to work zone and drop-off to valley below



Attachment 10 – Worker wearing harness but not tied off

