PHOTOGRAPHS: 41 ALCINA AVENUE

ATTACHMENT NO. 3



Front (North) Elevation, showing carport



Front (North) Elevation

# PHOTOGRAPHS: 41 ALCINA AVENUE

### ATTACHMENT NO. 3



Entry Door, West Elevation



Rear (South) Elevation

### ATTACHMENT NO. 3

# PHOTOGRAPHS: 41 ALCINA AVENUE



Interior Studio, Looking East



Interior Studio, Looking North

#### ATTACHMENT NO. 3

# PHOTOGRAPHS: 41 ALCINA AVENUE



Open staircase leading to Living Room from front door, West side



Combination Living and Dining Room, showing brick (North) wall with fireplace and cantilevered stone hearth