

York Wilson House, view of property looking south from Alcina Avenue (1997)



York Wilson House, Front (North) Elevation (1997)

## ATTACHMENT NO. 3

## PHOTOGRAPHS: 41 ALCINA AVENUE



York Wilson House, Rear (South) Elevation (1997)



York Wilson House, Rear (South) Elevation, Heritage Preservation Services (2016)

## ATTACHMENT NO. 3

## PHOTOGRAPHS: 41 ALCINA AVENUE



York Wilson House, view looking south at interior master bedroom balcony from entrance hallway, original design (1997)



York Wilson House, interior master bedroom balcony, existing condition, Heritage Preservation Services (2016)