

Attachment 1: Photographs of Western Beaches Breakwaters



Photo of mid-section of Western Beaches breakwaters, across from Cazsimir Gzowski Park Beach.



Photo of Western Beaches breakwaters located in Lake Ontario south of Toronto shoreline.



Photo of significant local deterioration of cap block.



Photo of extensive damage near west end of structure.




Photo of extensive damage to concrete cap and substructure.



Photo of damage to concrete cap.