

# **Area Tour - September 2004**

Gardiner East Contaminated Soil  
Monitoring and Review Committee

Gardiner East Contaminated Soil Monitoring and Review Committee - September 2004 Site Tour



Areas A & B are monitored by a public committee

**Gardiner East Contaminated Soil Monitoring and Review Committee - September 2004 Area Tour**



Both Areas A & B are part of busy recreational trails used for bicycling, roller blading and running.





Planted grasses and vegetation have taken hold and doing well.



Area B - located at Lakeshore Blvd East and Leslie Street, south east corner

## Gardiner East Contaminated Soil Monitoring and Review Committee - September 2004 Area Tour



Members of the committee, and city of Toronto staff, review the areas - September 2004.

Contaminated soil is capped and contained within the sites. Vegetation is growing well and soil cover is intact - September 2004.



Gardiner East Contaminated Soil Monitoring and Review Committee - September 2004 Area Tour



Centre meridian is part of Area A

Ground water is monitored to ensure contaminates are not entering the groundwater.



Monitoring well cap



Gardiner East Contaminated Soil Monitoring and Review Committee - September 2004 Area Tour



Committee member  
William Brown inspects  
Area A - September 2004

Community art tiles mark the north west corner of Leslie Street and Lakeshore Ave. The tiles commemorate the dismantling of the east section of the Gardiner Expressway - 2000

