


Taylor Massey Creek Sub-Watershed Master Plan Update

Geomorphic Issues and Constraints




- Key Map**
- Planned Stream Restoration Projects (1-5 years horizon)
 - Sanitary Trunk Sewer
 - Stormwater Management Facility
 - Crossings - Replaced
 - Crossings - Undersized
 - TRCA Floodline
 - TRCA Floodplain
 - Cemetery
 - Golf Course
 - Parks
 - Creeks
 - ESA Boundary
 - Taylor Massey Sub-Watershed Study Area

Geomorphic Issues:

- Pedestrian bridge / pad / weir repair
- Failing gabions / bank protection required
- Exposed pipe / culvert / sanitary sewer
- Sand / sediment deposit or vegetation in creek
- Deteriorated retaining wall / bank erosion
- Debris / log jam
- Manhole / deteriorated outfall
- Other



SCHOLLEN & Company Inc.
30 Wertheim Court, Unit 15
Richmond Hill, Ontario L4B 1B9
Tel: 289-695-0009
Fax: 289-695-0010
Email: design@schollenandcompany.com



0 250 500 1,000 Meters

June 21, 2017

