## April 3, 2018

# Glen Cedar Road Bridge Rehabilitation over Cedarvale Ravine

Contract 17ECS-TI-03BE Start Date: December 4, 2017 Expected End Date: July 20, 2018 \*Timeline is subject to change.

This notice serves as an update to the work taking place on the Glen Cedar Road Bridge over Cedarvale Ravine and nearby staircase. On April 30, the Contractor will begin the work on the east portion of the bridge, the walkway approaches and the nearby staircase.

This work will ensure that the bridge and the staircase meets today's standards and remains safe for public into the future. Further notice will be distributed and signage will be posted before the approach pathway re-construction work takes place in July of 2018.

### MAP OF WORK AREA



#### WORK DETAILS

#### To date, the contractor has started the following work:

- Replace the bridge deck and sidewalks on the west portion of bridge;
- Replace the railing and lighting system on the west portion of the bridge;
- Clean and coat structural steel on the west portion of the bridge; and
- Repair the piers and abutments on the west portion of the bridge.

# On April 30, the contractor plans to switch to the east side of the bridge and begin the following work:

- Rehabilitate east portion of the bridge including replacement of new timber bridge deck and sidewalk, metal railing, and light poles;
- Clean and coat structural steel on the remaining portion of bridge;
- Replace the approach pathway; and
- Replace the northeast staircase.

#### WHAT TO EXPECT DURING CONSTRUCTION

• You may experience dust, noise and other inconveniences. The Contractor will make efforts to reduce impacts. We appreciate your patience.

<b>÷</b>	<b>Bridge and Staircase Access:</b> In order to complete the work in a safe manner, there will be access restrictions within the construction work area including sections of the bridge and the staircase. Please note that pedestrian access across the bridge will be maintained when possible. Pedestrians will have to alternate the side of the bridge they use based on the work zone location at that time.
	<b>Work Hours:</b> Work on this project will take place from 7:00 a.m. to 5:30 p.m., Monday to Friday. Work will be performed after hours and on weekends as required.
六	<b>Bridge Access:</b> Pedestrians will use the west side of the bridge for access. There will be no access to the bridge <b>(for approximately one week)</b> in order to complete work on the bridge approach pathways. A Construction Update will be distributed before the approach pathway reconstruction.
~ •	<b>Staircase Access:</b> There will be no access between the bridge and Cedarvale Park Trail.
	<b>Trail Safety:</b> Pedestrians will use the hoarding system erected below the bridge on the Cedarvale Park Trail.
8	<b>Traffic Management:</b> Traffic should not be impacted by this work. Residents of the area may notice the presence of construction traffic (vehicles, materials, etc.) at Cedarvale Park and trail, and on Strathearn Road, Heathdale Road, Connaught Circle, and Glen Cedar Road.
	Restoration: Areas affected by construction will be restored.

#### NEED MORE INFORMATION?

If you have questions about the upcoming work, please contact us.

Project Manager	Sun Wai Lee, 416-392-8312, swlee@toronto.ca
TTY Hearing Impaired	416-338-0889
Service	(7 Days a week, 8:00 am – 5:00 pm, closed holidays)
General inquiries	311
Website	toronto.ca/improvements/ward21.htm

Thank you for your patience. Building a great city takes time. Better infrastructure for all of us is worth the wait.