

Rosehill Reservoir Rehabilitation & David A Balfour Park Installation

Community Update #38 – Photo Update
June 4, 2021

PUBLIC
AND PRIVATELY
NOT ALLOWED
ON THIS SLOPE

PLEASE
KEEP TO THE
WALKS



Garden walkways to be installed this weekend



Installing walkways



Growing medium installed in the Garden Beds



Sodding installed near the east side of the Upper Path
(Looking southwest and west from Avoca)



East side of the Washroom



Enclosure may be needed for some finishing work

Sodding on plateau and south side slope near the Valve House.
Some exterior work on the Access House.
(looking west)



Sprinkler to water
the grass

Sodding installed near the Lower perimeter pathway

Left Photo: near the east side

Right Photo: near the playground



Upper pathway installed at the Valve House Stairs
(facing south towards Summerhill entrance/Little Park)



New Plantings

